East Midlands Gateway Phase 2 (EMG2)

Document DCO 6.14/MCO 6.14

ENVIRONMENTAL STATEMENT

Volume 1 Main Statement

Chapter 14

Ground Conditions

July 2025

The East Midlands Gateway Phase 2 and Highway Order 202X and The East Midlands Gateway Rail Freight and Highway (Amendment) Order 202X



14. Ground Conditions

14.1. Introduction

- 14.1.1. This chapter of the ES assesses any potential effects relating to the existing ground conditions, geological setting, hydrogeology and land contamination aspects of the EMG2 Project, as described in full in Chapter 3: Project Description (Document DCO 6.3/MCO 6.3).
- 14.1.2. In summary, the **EMG2 Project** comprises the three components presented within **Table**14.1 below, forming the DCO and MCO Applications / Schemes.

Table 14.1: EMG2 Project Components

Main	Details	Works Number*			
Component					
DCO Applica	tion / DCO Scheme				
EMG2	Logistics and advanced manufacturing	DCO Works Nos. 1 to			
Works	development located west of the M1 Motorway	5.			
	and south of East Midlands Airport.				
	Upgrade to the EMG1 substation and provision	DCO Works Nos. 20			
	of a community park.	and 21.			
Highway	Works to the highway network, comprising	DCO Works Nos. 6 to			
Works	significant improvements at Junction 24 of the	19.			
	M1 (referred to as 'Junction 24 Improvements')				
	and works to the wider highway network				
	(construction of highway infrastructure to				
	facilitate access to the EMG2 Works,				
	specifically the EMG2 Main Site).				
MCO Applica	ation / MCO Scheme	<u> </u>			
EMG1	Additional warehousing development on Plot 16	MCO Works Nos. 3A,			
Works	together with works to increase the permitted	3B, 5A, 5B, 5C, 6A			
	height of the cranes at the EMG1 rail-freight	and 8A.			
	terminal, improvements to the public transport				
	interchange, site management building and the				
	access works.				
Notes:					
*Works Number is informed by the EMG2 Project Components Plan (Document					
DCO/MCO 2.	7).				

- 14.1.3. This chapter describes the methodology of assessment, the current baseline conditions, any likely significant environmental impacts, the mitigation measures intended to avoid, minimise or remedy the identified impacts, and the residual effects post implementation of these measures.
- 14.1.4. This chapter should be read in conjunction with the following supporting information, provided within Appendix 14A to 14M (Documents DCO 6.14A to 6.14M) as follows:

EMG2 Works (DCO Application):

- Appendix 14A (Document DCO 6.14A/MCO 6.14A): Fairhurst, East Midlands Gateway Phase 2, Land south of East Midlands Airport, Derby, Phase 1 Geo-Environmental and Geotechnical Preliminary Risk Assessment (Ref. 148749/R5, dated August 2024);
- Appendix 14B (Document DCO 6.14B/MCO 6.14B): Fairhurst, East Midlands Gateway Phase 2, Land south of East Midlands Airport, Derby, Ground Investigation Report (Ref. 148749/R7.1, dated August 2024);
- Appendix 14C (Document DCO 6.14C/MCO 6.14C): Fairhurst, East Midlands Gateway Phase 2, Land south of East Midlands Airport, Derby, Minerals Safeguarding Assessment (Ref. 148749/R5, dated July 2024);
- Appendix 14D (Document DCO 6.14D/MCO 6.14D): Fairhurst, EMG Phase 2, Derby, Technical Note: Surface Water Sampling (Ref. 146959, TN01_Rev2, dated October 2024)

Highway Works (DCO Application)

- Appendix 14E (Document DCO 6.14E/MCO 6.14E): BWB East Midlands Gateway
 Phase 2, Preliminary Sources Study Affecting Leicestershire County Council (Ref No.
 220500, dated March 2025);
- Appendix 14F (Document DCO 6.14F/MCO 6.14F): BWB East Midlands Gateway Phase 2, Preliminary Sources Study Affecting National Highways (Ref No. 220500, dated March 2025);
- Appendix 14G (Document DCO 6.14G/MCO 6.14G): BWB East Midlands Gateway
 2, Geotechnical Statement of Intent for Works Affecting National Highways (Ref No. 220500, dated March 2025).

EMG1 Works (MCO Application)

- Appendix 14H (Document DCO 6.14H1/MCO 6.14H): Fairhurst, East Midlands Gateway Phase 2, Land south of East Midlands Airport, Derby, Addendum Minerals Safeguarding Assessment (Ref.148748/R9, dated November 2024);
- Appendix 14I (Document DCO 6.14I/MCO 6.14I): RSK Ltd East Midlands Gateway Strategic Rail Freight Interchange, Zone 1 Main Development Plateau and Rail Freight Terminal, Factual Ground Investigation Report (Ref. 312494-01-02 (00), dated December 2013);
- Appendix 14J (Document DCO 6.14J/MCO 6.14J): RSK Ltd East Midlands Gateway Strategic Rail Freight Interchange, Zone 1 Main Development Plateau and Rail Freight Terminal, Preliminary Ground Investigation Interpretative Report (Ref. 312494/1-03(00), dated December 2013);

Regulatory Correspondence:

- Appendix 14K (Document DCO 6.14L/MCO 6.14K): Leicestershire County Council
 Mineral and Waste Planning Authority (MWPA) email correspondence decision to
 scope out minerals safeguarding from the ES chapter (dated December 2024);
- Appendix 14L (Document DCO 6.14L/MCO 6.14L): Mining Remediation Authority
 email correspondence decision to scope out risks associated with coal mining features
 at the surface or at shallow depth from the ES chapter (dated February 2025).

Figures - Appendix 14M (Document DCO 14M/MCO 14M):

DCO Application:

- Figure 14M.1: EMG2 Works Potential Sources of Contamination Plan;
- **Figure 14M.2**: **EMG2 Works** Exploratory Hole Location Plan with Proposed Development;
- **Figure 14M.3**: **EMG2 Works** Cross Sections Plan and corresponding cross sections;
- **Figure 14M.4**: **EMG2 Works** Groundwater Levels Plan with Proposed Development;
- Figure 14M.5: EMG2 Works Cut and Fill Analysis Plan;
- Figure 14M.6: EMG2 Works Isopachytes; and
- Figure 14M.7: EMG2 Works Finished Levels.

MCO Application:

- Figure 14M.8: EMG1 Works Exploratory Hole Location Plan.
- 14.1.5. This Chapter provides an assessment of the ground conditions at the land within the DCO Application comprising the EMG2 Works and Highways Works and also the land upon which the EMG1 Works are to be constructed pursuant to the MCO Application. The corresponding Parameters Plans are presented within Document DCO 2.5 and MCO 2.5. The Highway Works General Arrangement Drawings are provided as Document DCO 2.8.

14.2. Scope and Methodology of the Assessment

14.2.1. To inform the assessment, the existing land use, soil, geological, hydrological and hydrogeological conditions have been reviewed for both the DCO and MCO Application. For the DCO Application, the Preliminary Risk Assessment Report at Appendix 14A (Document DCO 6.14A) and Ground Investigation Report at Appendix 14B (Document DCO 6.14B) have been reviewed for the EMG2 Works, as well as the Preliminary Sources Study Reports (PSSRs) completed by BWB for the Highways Works provided at Appendix 14E and 14F (Documents DCO 6.14E and DCO 6.14F). For the MCO Application, the Preliminary Ground

- Investigation Interpretative and Factual Reports at Appendix 14I and 14J (Documents MCO 6.14F and MCO 6.14J) have been reviewed for the (EMG1 Works).
- 14.2.2. The process of Land Contamination Risk Management (LCRM) has been generally adhered to, where a ground investigation has been undertaken to characterise potential contaminant linkages identified within the Preliminary Risk Assessment, and subsequent refinement of the assessment completed through intrusive investigation to further characterise the ground conditions and present associated mitigation, as required.

Scoping Consultation

- 14.2.3. A Scoping Report (**Document DCO 6.1C/MCO 6.1C**) on behalf of the Applicant was submitted to PINS in August 2024, in which Fairhurst proposed the 'scoping out' of ground conditions / contamination pertaining to the **EMG2 Works** of the DCO Application.
- 14.2.4. A Scoping Opinion was adopted by PINS on the 24th of September 2024 (Document DCO 6.1D/MCO 6.1D). Table 14.2 below summarises the comments from the Scoping Opinion accompanied by relevant commentary.

Table 14.2: Scoping Opinion Comments and Commentary

Originator	Details	Commentary
PINS	Stated that ground conditions and	This ground
ID 3.1.2	contamination should not be scoped out of the	conditions chapter
	assessment, due to the fact that the scoping	has been prepared
	report does not provide evidence of the land	considering the EMG2
	use history for the EMG2 Works nor any	Works, Highways
	information in relation to EMG1 Works and	Works and EMG1
	Highway Works. The Ground Investigation	Works (including Plot
	Report also identifies Made Ground within	16), pertaining to the
	areas currently identified as agricultural land	DCO and MCO
	within the EMG2 Works, indicating that infilling	Applications,
	may have occurred.	respectively.
PINS ID	Stated that the Minerals Assessment Report	Fairhurst prepared an
3.03	does not extend to the Highway Works or	Addendum Minerals
	EMG1 Works.	Safeguarding
		Assessment (dated
		November 2024),
		which covers the
		Highways Works and
		EMG1 Works
		(Appendix 14H-
		Document DCO
		6.14H/MCO 6.14H)
		and submitted this to
		Leicestershire County
		Council (see below).

Originator	Details	Commentary
Leicestershire	Confirmed that there are no objections from a	Minerals
County	mineral safeguarding perspective and is	Safeguarding has not
Council	satisfied that minerals safeguarding can be	been considered
	scoped out of the ground conditions chapter,	further.
	following receipt of the Fairhurst Addendum	
	Minerals Safeguarding Assessment. This	
	response is presented within Appendix 14K -	
	Document DCO 6.14K/MCO 6.14K.	
Mining	Confirmed that the EMG2 Project is not	Potential risks
Remediation	located within an area where records indicate	associated with coal
Authority	coal mining features at surface or at shallow	mining features have
	depth are present (i.e. the EMG2 Project is	not been considered
	located outside of the defined coalfield). This	further.
	response is presented within Appendix 14L -	
	Document DCO 6.14L/MCO 6.14L.	

Statutory Consultation

- 14.2.5. A six-week period of statutory consultation was undertaken between Monday 3rd February 2025 and Monday 17th March 2025. This included the presentation of draft application material for the **EMG2 Project**, including draft ES Chapters.
- 14.2.6. The responses are summarised within **Table 14.3** below, accompanied by the ways in which the responses have been addressed in this iteration of the chapter.

Table 14.3 Statutory Consultation Commentary

Originator	Details	Commentary	
Environment	The EA have requested	Preliminary Sources Study Reports (PSSRs)	
Agency	additional information in	pertaining to the Highway Works have	
	regard to the ground	been reviewed to inform the ground	
	conditions and land	conditions in this part of the EMG2 Project	
	contamination risks	(Appendix 14E and 14F).	
	pertaining to the		
	Highway Works.		
	The EA have provided	The sensitivity of the Secondary Aquifers	
	comment on the	has been reconsidered and updated, and is	
	sensitivity classification	presented within Table 14.4 of this Chapter.	
	of some Secondary		
	Aquifers.		
	The EA have suggested	This has been reviewed and referenced	
	the 'Environment Agency	within Paragraph 14.3.22.	
	Groundwater Protection		
	Position Statements'		
	should be reviewed to		
	inform the risk to		
	groundwater beneath the		
	EMG2 Project.		

Originator	Details	Commentary
	The EA have requested	Fairhurst has provided the data requested
	to be provided with the	by the EA which supports the fact that the
	source data pertaining to	Waste Transfer Station is a geo-referencing
	the Waste Transfer	error. This was accepted by the EA on 21st
	Station on the EMG2	April 2025.
	Works, suspected to be	•
	a geo-referencing error.	
	The EA have requested	This has been added to the Chapter, with
	additional information	additional information regarding the
	regarding the	locations of the monitoring points, duration
	groundwater monitoring	of the monitoring and the time of year it was
	completed at the EMG2	undertaken.
	Works.	Shallow groundwater encountered as part of
		the monitoring has also resulted in the
		consideration of dewatering in the
		earthworks (Paragraph 14.6.8).
		Appendix 14M. Figure 14M.4 presents a
		Groundwater Levels Plan with Proposed
		Development at the EMG2 Works , which
		shows the locations and monitored levels at
		the groundwater monitoring wells.
	The EA have requested	This has been added to the Chapter, with
	additional information	Tables 14.5 and 14.14 presenting the types
	regarding the soil testing	of laboratory test and number of tests
	which has been	completed.
	undertaken as part of the	
	ground investigations.	
	The EA have requested	This has been added to the Chapter,
	clarification of the range	whereby 15 No. groundwater samples were
	in depth at which the	obtained (both from the shallow
	groundwater samples	groundwater body and the deeper
	were obtained from the	groundwater body) from selected monitoring
	EMG2 Works.	wells at the EMG2 Works at depths of
		between 2.51 m bgl and 19.00 m bgl
		(Paragraph 14.4.18).
	The EA have requested	This Chapter has been updated to include a
	more information	Table which indicates the findings of the
	regarding the	controlled waters assessment, including a
	groundwater Polycyclic	summary of the groundwater chemical
	Aromatic Hydrocarbon	exceedances with the determinant
	exceedance against the	exceedance, contaminant range, number of
	relevant Generic	elevated results and relevant GAC (Table
	Assessment Criteria.	14.6). The laboratory groundwater results
		are presented within Appendix C of the
		EMG2 Works Ground Investigation Report
		(Appendix 14B).
		(Appendix 140).

Originator	Details	Commentary
	The EA have requested more information regarding the surface water sampling completed as part of the EMG2 Works Ground Investigation.	Additional information has been added to this Chapter, including the locations of the surface water samples, a summary of surface water chemical exceedances (Table 14.7), and consideration of the sample exceedance being upstream or downstream of the other sample. Further surface water sampling and testing has also been discussed with the findings presented within the Fairhurst Surface Water Sampling Technical Note (Appendix 14D).
	The EA has requested further consideration and acknowledgement regarding the identified groundwater contamination.	Further consideration has been given, and the Chapter has been updated accordingly with reference to the type of groundwater contamination and its potential to reach surface water receptors.
	The EA have requested clarification on the thickness of the Made Ground encountered.	The Chapter has been updated, with references to the 'significance' of Made Ground thickness updated.
	The EA have requested consideration of the reuse of site won materials and waste.	This has been added to the Chapter, see Paragraphs 14.6.5 to 14.6.7. It is considered that the Made Ground may be re-used as part of the earthworks, subject to appropriate sorting, segregation and classification testing and controlled placement in accordance with an earthworks specification and associated Materials Management Plan or environmental permit as appropriate (subject to Chapter 18: Materials and Waste).
North West Leicestershire District Council	The Environmental Protection (Contaminated Land) Officer raised concerns that CIRIA C665 is used for ground gas assessment rather than the British Standard 8485 and therefore the Chapter should be updated to reflect the more recent guidance	The Chapter has been updated accordingly to use BS 8485 when assessing ground gases.

- 14.2.7. Therefore, taking into consideration the above consultation and statutory comments, this Chapter assesses the likely significant effects on ground conditions of the following:
 - a. The DCO Scheme comprising the **EMG2 Works** and **Highways Works** within the DCO Application;
 - b. The MCO Scheme comprising the EMG1 Works within the MCO Application; and
 - c. The **EMG2 Project** comprising the DCO Scheme and MCO Scheme together and the intra-project combined effects.
- 14.2.8. The baseline conditions for the **EMG2 Works**, **Highway Works** and **EMG1 Works** have been established through existing data referenced within Paragraph 14.1.4 and included within the appendices of this Chapter. This data is discussed further within Section 14.4.

Prediction Methodology

- 14.2.9. The sensitivity of potentially affected receptors will be considered on a scale of high, moderate or low, with the associated definitions as follows:
 - High sensitivity: the receptor / resource has little ability to absorb change without fundamentally altering its present character, or is of international or national importance.
 - Moderate sensitivity: the receptor / resource has moderate capacity to absorb change without significantly altering its present character, or is of high importance.
 - Low sensitivity: the receptor / resource is tolerant of change without detriment to its character, or is of low or local importance.
- 14.2.10. Typical examples of sensitivity are listed in **Table 14.4** below and sensitivities of site specific receptors are listed within **Table 14.14**.

Table 14.4: Receptor Sensitivity Criteria

Receptor	Human Health	Built Environment /	Controlled Waters
Sensitivity		Infrastructure	
High	On-site users, off-	Residential, gas/oil	Aquifers currently in use or
	site residential,	infrastructure /	are suitable for use, as public
	youth,	pipelines, mainline	potable supplies (Principal
	construction	railway lines, power	Aquifers, EA designated
	workers assuming	transmission lines, A	SPZs), waters of national
	no use of PPE.	roads, dual	designated areas (SSSI,
		carriageway, B roads,	RAMSAR, SAC).
		local power lines.	
Moderate	Non-residential	More minor C roads,	Secondary Aquifer which
	off-site users,	local services.	supports abstraction for
	POS users,		agricultural (irrigation) or
	construction		industrial use, controlled
	workers assuming		waters of regionally
	PPE use.		designated areas (e.g. local
			nature reserves).

Receptor	Human Health	Built Environment /	Controlled Waters
Sensitivity		Infrastructure	
Low	Limited access /	Non-permanent /	Undifferentiated and
	exposure /	temporary structures.	Unproductive Stratum,
	unoccupied land.		undesignated site or
			controlled water features
			which considerable enrich
			the local habitat.

- 14.2.11. The magnitude of change will be qualitatively described and categorised based on the terminology set out in ES **Chapter 1: Introduction** of this ES (**Document DCO 6.1/MCO 6.1**).
- 14.2.12. The construction and operational phases will be considered in the assessment of any potential impacts and likely effects. The level of significance allocated to each identified effect will be assessed on the basis of the magnitude of change and the sensitivity of the affected receptor to that change.
- 14.2.13. The assessment of significance is based on the 'Effect Significance Matrix' presented within ES **Chapter 1: Introduction (Document DCO 6.1/MCO 6.1)**. Effects which are 'Moderate' or greater are considered to be significant in the view of the EIA Regulations.
- 14.2.14. The below terms will be used to define the significance of the identified effects:
 - Major beneficial or adverse effect where the effects would result in a large enhancement (or deterioration) to the current environment;
 - Moderate beneficial or adverse effect where the effects would result in a medium enhancement (or deterioration) to the current environment;
 - Minor beneficial or adverse effect where the effects would result in a small enhancement (or deterioration) to the current environment; and
 - Negligible where the effects will not result in a noticeable enhancement or deterioration.
- 14.2.15. The anticipated effects can be of differing duration; short term, medium term or long term. The duration of impacts is anticipated within the below sections of this chapter, with the definitions of each duration presented within ES Chapter 1: Introduction (Document DCO 6.1/MCO 6.1).
- 14.2.16. The prediction methodology associated with ground conditions and contamination will be completed by comparing the baseline conditions (based on Ground Investigation information) with the conditions during the construction phase as well as the conditions post-development, incorporating the potential magnitude of change and the sensitivity of receptors. It should be noted that the baseline conditions pertaining to the Highway Works has been informed by the Preliminary Sources Study Reports (PSSRs) which comprise mainly desk based information. To start with, the assessment will evaluate the significance of the likely effect, considering both inherent (i.e. the implementation of mitigation measures which would be incorporated into the design and incorporated (i.e. mitigation which would be

expected to be achieved through adhering to best practise and the requirements set out within the DCO) mitigation measures that would be applied.

Limitations and Assumptions

14.2.17. This Chapter has been prepared in accordance with good general practise and guidance and is based upon ground investigation data which is available at the time of writing only. Consideration should be given to any changes in industry practises or legislation subsequent to the date of issue of this Chapter.

14.3. Policy, Guidance and Legislative Context

14.3.1. The Ground Conditions and Contamination assessment has been undertaken considering relevant planning policies and published guidance documentation and legislation. These are summarised below.

Legislation and Regulation

- 14.3.2. The assessment within this Chapter has been performed cognisant of the requirements in the following legislation:
 - Part 2A of the Environmental Protection Act (EPA) 1990;
 - The Town and Country Planning Act 1990;
 - The Water Resources Act 1991;
 - The Planning Act 2008 (as amended);
 - The Contaminated Land (England) (Amendment) Regulations 2012;
 - The Control of Asbestos Regulations 2012; and
 - The Water Framework Directive 2017.

Planning Policy

14.3.3. The following planning policy documents are relevant and have informed the assessment.

National Networks National Policy Statement (NNNPS)

14.3.4. NNNPS Guidance (March 2024), presented to Parliament pursuant to Section 9(8) of the Planning Act, includes various general impacts and corresponding mitigations of national road, rail and strategic rail freight interchange (SRFI) developments. Extracts relevant to this assessment are discussed below.

Land Contamination and Instability:

14.3.5. Paragraph 5.154: "Where necessary, land contamination and instability should be considered in respect of new development. Specifically, the proposals should be appropriate for the location, including preventing unacceptable risks from land contamination or instability. If land instability and/or land contamination may be an issue, applicants should seek appropriate technical and environmental expert advice from a competent person to

- prepare and carry out the appropriate assessments. Applicants should consult with the Coal Authority, Environment Agency and Local Authority if necessary."
- 14.3.6. Paragraph 5.155: "For developments on previously developed land, applicants should ensure and demonstrate that they have considered the risks posed by land contamination in accordance with the Land Contamination Risk Management guidance115. A preliminary assessment of land contamination and/or ground instability should be carried out at the earliest possible stage before a detailed application for development consent is prepared."
- 14.3.7. Paragraph 5.156: "Applicants should ensure that any necessary investigations are undertaken, in accordance with Land Contamination Risk Management guidance, to ascertain the risk from contamination and identify sensitive receptors and that their sites are, and will, remain stable or can be made so as part of the development. The site needs to be assessed in the context of surrounding areas where subsidence, landslides and land compression could threaten the development during its anticipated life or damage neighbouring land or property. This could be in the form of a land stability or slope stability risk assessment report."
- 14.3.8. The following land contamination and instability mitigation measures are stated within the guidance:

Instability

- 14.3.9. Paragraph 5.157: "Applicants have a range of mechanisms available to mitigate and minimise risks of land instability. These include:
 - establishing the principle and layout of new development, for example avoiding mine entries and other hazards
 - ensuring proper design of structures to cope with any movement expected, and other hazards such as mine and/or ground gases
 - requiring ground improvement techniques, usually involving the removal of poor material and its replacement with suitable inert and stable material, for development on land previously affected by mining activity, this may mean prior extraction of any remaining mineral resource"
- 14.3.10. Paragraph 5.158: "Applicants should submit a coal mining risk assessment as part of their application in specific Development High Risk areas."

Land Contamination

- 14.3.11. Paragraph 5.159: "Applicants have a range of options available to mitigate and minimise risks of land and groundwater contamination:
 - these options should include sustainable remediation, sustainable remediation can provide the opportunity to manage unacceptable risks to human health and the environment, it can help to ensure that the benefit of doing the remediation is greater than its impact
 - in accordance with the Environmental Improvement Plan, disposal of soils to landfill should be minimised."

National Planning Policy Framework (NPPF) 2024

14.3.12. The National Planning Policy Framework, (NPPF) updated in December 2024 provides the following with reference to contamination and ground conditions:

Paragraph 187: "Planning policies and decisions should contribute to and enhance the natural and local environment by:

- a) protecting and enhancing valued landscapes, sites of biodiversity or geological value and soils (in a manner commensurate with their statutory status or identified quality in the development plan);
- e) preventing new and existing development from contributing to, being put at unacceptable risk from, or being adversely affected by, unacceptable levels of soil, air, waterer or noise pollution or land instability. Development should, wherever possible, help to improve local environmental conditions such as air and water quality, taking into account relevant information such as river basin management plans; and
- f) remediating and mitigating despoiled, degraded, derelict, contaminated and unstable land, where appropriate."

Paragraph 196: "Planning policies and decisions should ensure that:

- a site is suitable for its proposed use taking account of ground conditions and any risks arising from land instability and contamination. This includes risks arising from natural hazards or former activities such as mining, and any proposals for mitigation including land remediation (as well as potential impacts on the natural environment arising from that remediation);
- b) after remediation, as a minimum, land should not be capable of being determined as contaminated land under Part IIA of the Environmental Protection Act 1990; and
- adequate site investigation information, prepared by a competent person, is available to inform these assessment."

Paragraph 197: "Where a site is affected by contamination or land stability issues, responsibility for securing a safe development rests with the developer and/or landowner." *National Planning Practice Guidance*

14.3.13. Paragraph 002 (Ref ID. 33-002-20190722) of the National Planning Practice Guidance on Land Affected by Contamination (2019) lists the actions to be taken by local planning authorities in order to determine planning applications with regards to land affected by contamination.

North West Leicestershire Local Plan

14.3.14. The site baseline conditions have also considered the local plan prepared by North West Leicestershire District Council which sets out current planning policies for the District from 2011 to 2031 (adopted in 2017 and underwent partial review in 2021). Policy En6 (Land and Air Quality) is relevant to and has informed this Chapter

14.3.15. Policy En6 – Land and Air Quality:

"Proposals for development on land that is (or is suspected of being) subject to land instability issues or contamination, or is located within the defined Development High Risk Area or within or close to an Air Quality Management Area or close to a known source of noise will be supported where:

- (a) A planning application is accompanied by a detailed investigation and assessment of the issues; and
- (b) Appropriate mitigation measures are identified which avoid any unacceptably adverse impacts upon the site or adjacent areas, including groundwater quality.

Development should avoid any unacceptably adverse impact upon soils of high environmental value (for example wetland or other specific soils) and ensure that soil resources are conserved and managed in a sustainable way."

- 14.3.16. Paragraph 10.45 states that "North West Leicestershire has a long history of coal mining and heavy industry. This has left a legacy of potential land instability and contamination issues. The Coal Authority has defined a 'Development High Risk Area' that covers most of the district. In this area the potential land instability and other safety risks associated with former coal mining activities are likely to be greatest. They include, for example, areas of known or suspected shallow coal mining, recorded mine entries and areas of former surface mining. Other than householder developments and those exceptions as identified on the Coal Authority's exemptions list, all new development proposals within the defined Development High Risk Area must be supported by a Coal Mining Risk Assessment, or equivalent, in order to identify any potential risks to the new development and any required remediation measures. These assessments must be carried out by a suitably qualified person to the current British Standards and approved guidance."
- 14.3.17. Paragraph 10.47 notes that "Groundwater provides a third of our drinking water in England and Wales, and it also maintains the flow in many of our rivers. It is crucial that we look after these sources and ensure that water is completely safe to drink".

Technical Standards and Guidance

- 14.3.18. Technical documents produced by the British Standards Institute (BSI) and of relevance include standards for the investigation of potentially contaminated sites in order that appropriate actions can be taken:
 - BS10175:2011+A2:2017. Investigation of Potentially Contaminated Sites Code of Practice;
 - BS8485:2015:A1:2019. Code of Practice for the design of protective measures for methane and carbon dioxide ground gases for new buildings; and
 - BS5930: 2015+A1:200. Code of Practice for Site Investigations.
- 14.3.19. CIRIA provides a plethora of technical guidance documents to assess the potential risks to new structures and encourage safe site working. Documents which may be relevant to this ES Chapter include:

- CIRIA C552:2001: Contaminated Land Risk Assessment: A Guide to Good Practice;
- CIRIA C681: Unexploded Ordnance (UXO): A Guide for the Construction Industry.
- CIRIA C733: Asbestos in Soil and Made Ground: A Guide to Understanding and Managing Risks;
- CIRIA C762: Environmental good practice on site pocked book; and
- CIRIA Report R13D: A Guide for Safe Working on Contaminated Sites.
- 14.3.20. The Environment Agency's Pollution Prevention Guidance (PPG) note series with additional related documents supply advice pertaining to the principles of pollution prevention, means to prevent contamination and guidance on responding to pollution incidents. Although the guidelines were withdrawn in 2015, they are still considered as good practice. The below PPGs and related documents are of relevance and thus have informed the assessment
 - PPG 1 Understanding Your Environmental Responsibilities Good Environmental Practices;
 - PPG 2 Above Ground Storage Tanks;
 - PPG 6 Working at Construction or Demolition sites;
 - PPG 21 Pollution Incident Response Planning;
 - Pollution Prevention Pays;
 - Prioritisation and categorisation procedure for sites which may be contaminated CLR
 6; and
 - Piling and Penetrative Ground Improvement Methods on Land Affected by Contamination: Guidance on Pollution Prevention.
- 14.3.21. The Environment Agency also provides guidance pertaining to the risk based assessment / quantitative refinement of the initial site conceptual model for contaminated sites. The below documents and guidance are considered vital to this refinement and have informed this assessment:
 - Updated Technical Background to the CLEA Model. Science Report SC050021/SR2;
 - Human Health Toxicological Assessment of Contaminants in Soil. Science Report SC050021/SR2;
 - The UK Approach for Evaluating Human Health Risks from Petroleum Hydrocarbons in Soils. Science Report P5-080/TR3;
 - Verification of Remediation of Land Contamination. Report SC030114;
 - Land Contamination Risk Management webpage, formerly CLR11 (LCRM) (2023);
 and
 - Groundwater Protection Position Statements (February 2018 version 1.2).

14.4. Baseline Conditions

DCO Application - EMG2 Works

- 14.4.1. The Preliminary Risk Assessment (PRA) (Appendix 14A Document DCO 6.14A) informs the historical setting of the EMG2 Works. Historically, the site comprised undeveloped agricultural fields, with the presence of a stream in the south-eastern area, ponds within the north-east and south-east and a drainage ditch which extended into the western area. By 1921, a potential pump was identified at the pond in the north eastern area, with the addition of further smaller ponds on the site. By 1955, one of the ponds (adjacent to the south eastern corner) previously identified no longer features on available historical maps, and thus is assumed to have been infilled at desk study stage. A further pond was identified in available historical maps dated 1966 1969, located within the north eastern area. From 1972 2021, no additional significant changes were identified.
- Historically, the surrounding area featured agricultural land, with various commercial/light and industrial/heavy uses. The earliest available historical map dated 1883 indicates the presence of a brick yard located 100 m south west (present until 1921), small ponds within a 200 m radius and the Diseworth Brook 100 m south west. In 1955, an airfield is identified 400 m north of the site, subsequently extending to within 50 m north west by 1962, and labelled as East Midlands Airport in maps post 1966. By 1966, the construction of the M1 motorway was completed, located 100 m north-east of the site. Tanks were identified in available historical maps dated 1972, located 260 m north west of the site. From the 1980s, there is an evident increase in industrial use with the development of commercial / light industrial land uses within a 250 m radius. These land uses included a depot (250 m north west), unspecified works (190 m south west), Donington Park Service Station (adjacent north east) and additional unnamed buildings. By 2021, two sewage pumping stations are identified 240m west and 50m north east.
- 14.4.3. The PRA assessed the following potential sources of contamination based on available information at the time of writing:
 - On-site sources
 - Two Infilled clay pits in the northern site area;
 - Former diesel generator in the southern site area; and
 - Waste Transfer Site in the centre of the northern site area.
 - Off-site sources
 - Service station and associated amenities, 67 90 m north east;
 - Numerous works associated with East Midlands Airport, 80 160 m north;
 - Historical / current landfill site, 254 m north west
- 14.4.4. During the site reconnaissance on 1st July 2022, no evidence of the associated infrastructure of a Waste Transfer Station having historically been on site were noted, despite it being recorded on the associated Envirocheck Report. Therefore, it was suspected that this location record may be a geo-referencing error and is more likely associated with the handling of airport waste, on the East Midlands Airport site. Fairhurst has since provided

the EA with data which supports the fact that the Waste Transfer Station is a geo-referencing error. The data supporting this erroneous result was accepted by the EA on the 22nd April 2025. As a result, the Waste Transfer Station has been discounted as a potential source of contamination.

- 14.4.5. **Appendix 14M.1** (**Document DCO**) provides a visual representation of the identified potential sources of contamination on site and in the surrounding site area.
- 14.4.6. The initial PRA classified the majority of complete pollutant linkages as Moderate/Low or Low risk, Fairhurst recommended further investigation through intrusive methods, to enable refinement of the Initial Conceptual Site Model (CSM), and thus refinement of the site baseline conditions.

Site Investigation

- 14.4.7. A ground investigation was completed at the **EMG2 Works** between September 2022 and October 2022. A Ground Investigation Report (GIR) had been prepared subsequent to this, dated August 2024 (**Document DCO 6.14B**), and thus the information presented below is based on the 2024 assessment.
- 14.4.8. The ground investigation comprised:
 - buried utility service clearance
 - 27 No. cable percussive boreholes with rotary core follow on
 - 28 No. cable percussive boreholes
 - 38 No. mechanically excavated trial pits with 8 No. soakaway infiltration tests
 - 2 No. variable head permeability tests
 - 25 No. groundwater and ground gas monitoring well installations and 3 No. return visits for groundwater and ground gas monitoring, including the collection of 2 No. surface water samples
- 14.4.9. The GIR (Appendix 14B Document DCO 6.14B) indicates the ground conditions comprise:
 - Topsoil (proven from the surface to a maximum depth of between 0.10 m and 0.85 m bgl);
 - Isolated occurrences of Made Ground (proven to a maximum depth of between 0.20 m bgl to 3.00 m bgl, with), with the deepest occurrence noted at CP27 located within the south eastern area (3.0 m thickness) and at TP08 located within the north western area (2.80 m thickness). All remaining exploratory locations where Made Ground was encountered generally comprised of less than 1.0 m;
 - Superficial deposits of The Oadby Member and Glaciofluvial Deposits (proven to maximum depths of 16.40 m bgl and 17.30 m bgl, respectively); and
 - Bedrock geology of The Gunthorpe Member and Diseworth Sandstone (proven to a maximum depth of 18.50 m bgl for the former, with the maximum depth of the latter not proven)

- 14.4.10. Visual / olfactory evidence of contamination was not recorded in all but one of the exploratory positions during the ground investigation at the site. The only position where this was recorded was at CP27 (far south eastern corner) where an 'iridescent sheen and moderate to strong hydrocarbon odour' was noted within the Made Ground encountered from a depth of 0.30 m bgl to 3.00 m bgl. The source of this contamination is unknown but is stipulated to originate from the historical diesel power generator identified within the PRA, discussed within Section 14.4.3 above.
- 14.4.11. **Table 14.5** below summarises the soil, groundwater and surface water laboratory tests completed on the samples obtained during the **EMG2 Works** ground investigation. Paragraph 14.4.29 outlines the supplementary surface water sampling completed in 2024.

Table 14.5: Geo-Environmental Testing - EMG2 Works (DCO Application)

Oca Farring managet at	Normals are of Call	Newsbarat	Normals are of
Geo-Environmental	Number of Soil	Number of	Number of
Test	Tests	Groundwater	Surface Water
		Tests	Tests
Metals:	65	15	2
Arsenic, Barium,	(2 No. MG,		
Beryllium, Boron,	15 No. TS,		
Cadmium, Chromium	8 No. ODT,		
(total), Chromium III,	16 No. GFDU,		
Chromium VI, Copper,	23 No. WGM,		
Lead, Mercury, Nickel.	1 No. GUN)		
Selenium and Zinc			
Soil Organic Matter	65	-	
	(2 No. MG,		
	15 No. TS,		
	8 No. ODT,		
	16 No. GFDU,		
	23 No. WGM,		
	1 No. GUN)		
Total Petroleum	65	15	2
Hydrocarbon (TPH) -	(2 No. MG,		
Aliphatic and Aromatic	15 No. TS,		
Split using the Criteria	8 No. ODT,		
Working Group	16 No. GFDU,		
Methodology – and	23 No. WGM,		
BTEX	1 No. GUN)		
Polycyclic Aromatic	65	15	2
Hydrocarbons (PAH) –	(2 No. MG,		
Speciated (EPA 16)	15 No. TS,		
	8 No. ODT,		
	16 No. GFDU,		
	23 No. WGM,		
	1 No. GUN)		
Selected Volatile	29	15	2
Organic Compound	(2 No. MG,		
(VOC) and Semi-	2 No. TS,		
` ′	<u>'</u>		I

Geo-Environmental	Number of Soil	Number of	Number of
Test	Tests	Groundwater	Surface Water
1621	16212	Tests	
		rests	Tests
Volatile Organic	2 No. GFDU,		
Compounds (SVOCs)	23 No. WGM)		
Methyl Tert-Butyl Ether	63	15	2
(MTBE)	(2 No. MG,		
	13 No. TS,		
	8 No. ODT,		
	16 No. GFDU,		
	23 No. WGM,		
	1 No. GUN)		
Phenol	9	15	2
	(2 No. MG,		
	2 No. TS,		
	2 No. GFDU,		
	3 No. WGM)		
Asbestos Screen (with	2	-	-
quantification, if	(2 No. MG)		
required)			
OCP and OPP	-	14	2
Combined Pesticide			
Suite			
PCBs (16MS)	-	14	2

Notes:

TS: Topsoil, MG: Made Ground, ODT: Oadby Member, GFDU: Glaciofluvial Deposits, WGM: Weathered Gunthorpe Member, GUN: Gunthorpe Member

Risks to Human Health

- 14.4.12. Considering the proposed development across the site (shown in the Parameters Plan **Document DCO 2.5**), the laboratory soil analytical results were assessed against the Generic Assessment Criteria (GAC) for the commercial end use. Soil Organic Matter test results ranged between 0.2% and 6.1% with an average of 1.6%. Therefore, the LQM/CIEH 'Suitable 4 Use Levels' (S4ULs) were applied on the basis of a 1% SOM as a conservative approach.
- 14.4.13. Results indicate that all concentrations of contaminants analysed were below the commercial end use assessment criteria where, in the majority of instances, results were below the laboratory limit of detection. Therefore, the overall risks to future end users is considered as Low.
- 14.4.14. Soil concentrations recorded across the site were also compared against UKIWR "Guidance for the selection of Water Supply Pipes to be used in Brownfield Sites (Ref 10/WM/03/21)". Results of the assessment indicated 2No. exceedances for Polyethylene (PE) pipe and 1 No. exceedance for Polyvinyl Chloride (PVC) pipe specification. However, the use of upgraded drinking water supply pipes is not considered necessary, due to these

exceedances being identified within the Topsoil layer (likely stripped during the development as part of the cut and fill scheme) and due to the detection of a hotspot of contamination, identified at CP27 associated with elevated C5-10 and C16-40 aliphatic / aromatic hydrocarbons, whereby removal via excavation is recommended.

Risks to Controlled Waters

- 14.4.15. The initial PRA set out the hydrological and hydrogeological regime of the site. The report suggests a low/moderate risk to Controlled Waters, with regard to the following controlled waters receptors:
 - Groundwater within the superficial deposits (Secondary A and Secondary Undifferentiated Aquifers) and bedrock deposits (Secondary B Aquifer); and
 - Inland streams identified on and within the vicinity of the site.
- 14.4.16. 3 No. rounds of groundwater monitoring were completed at 15 No. locations across the site, dated 13/14th October, 26/27th October and 10th to 14th November 2022. The results of the monitoring indicate shallow groundwater water (perched and non-continuous within superficial deposits), for example at 1.25 m bgl within the Made Ground of CP27 and at 3.85 m bgl within the Glaciofluvial Deposits of CP16. Deeper groundwater (for example at 15.32 m bgl within BH10) was recorded within the underlying Secondary B Aquifer supported by the Weathered Gunthorpe and Gunthorpe Member. Although, it should be noted that this groundwater is not always particularly deep, due to the discontinuous coverage of superficial deposits, as well as the elevation change from north to south (Appendix 14M.6 Document DCO/MCO 6.14M).
- 14.4.17. **Appendix 14M.4 (Document DCO 6.14M)** presents a groundwater levels plan for the **EMG2 Works**, presenting the locations of each monitoring well and the measured groundwater elevations across each of the 3 No. rounds. The groundwater levels plan indicates a southerly groundwater flow.
- 14.4.18. 15 No. groundwater samples were obtained from selected monitoring wells (comprising both the shallow and deeper groundwater body) at depths of between 2.51 m and 19.00 m bgl, and were scheduled for the geo-environmental tests listed within **Table 14.5** above.
- 14.4.19. The chemical results from the groundwater laboratory tests were assessed against the UK Drinking Water Standards, or where unavailable, the World Health Organization Drinking Water Standards.
- 14.4.20. The assessment concluded that contaminant levels within groundwater samples were generally below the Generic Assessment Criteria for the majority of samples, with the exception of 7 No. Polycyclic Aromatic Hydrocarbon (PAH) exceedances. These exceedances are presented within **Table 14.6** below.

Table 14.6: Summary of Groundwater Chemical Exceedances

Determinant	Location of	Contaminant	GAC	for	PAHs
	exceedance / depth	Concentration (µg/l)	(µg/l)		
	of sample (m bgl)				
Acenaphthylene	CP06 / 8.07	0.15	0.1		
	BH06 / 19.00	0.13			
Naphthalene	CP06 / 8.07	1.14			
	BH06 / 19.00	0.95			
	BH09 / 15.00	0.14			
	BH25 / 5.05	0.24			
	BH21 / 10.44	0.23			
Pyrene	CP27 / 2.51*	0.13			

^{*}Obtained from the shallow groundwater. All remaining exceedances were recorded within the deeper groundwater.

- 14.4.21. These exceedances were generally detected in the deeper groundwater in the northern and southern parts of the site (CP06, BH06 and BH09) and (BH21 and BH25), respectively, with the exception of CP27 which was obtained from the shallower groundwater within the Made Ground. Greater PAH exceedances were noted within the deeper groundwater in the northern area (for example, CP06, 1.14 ug/l), with concentrations generally decreasing within samples obtained from the southern site area (for example, BH25, 0.24 ug/l). These exceedances are noted as localised due to them being surrounded by non-detects (for example the Pyrene exceedance noted within CP27 at 2.51 m bgl was not recorded within the nearby boreholes of BH24 at 4.56m bgl or BH25 at 5.05 m bgl.
- 14.4.22. Considering the absence of abstraction points within 1,000 m of the site, and the proposed betterment through managed drainage systems and reduced infiltration (**Chapter 13: Flood Risk and Drainage-Document DCO 6.13**), the risks to controlled water quality are considered to be low.

Risks to Surface Waters

- 14.4.23. The PRA identified 2 No. watercourses within influential distance of the site, the closest being the Diseworth Brook c. 248 m south west. The Diseworth Brook flows south easterly and intercepts the Long Whatton Brook c. 545 m south east of the site. The Long Whatton Brook appears to be partially fed by drainage ditches which converge in the south eastern corner of the site and continue off-site. As it has been identified that these ditches are in hydraulic connectivity with the shallow groundwater body, it is considered that there is a potential pathway for groundwater contamination to enter the nearby watercourses.
- 14.4.24. Therefore, 2 No. surface water samples were taken from the drainage ditch (noted to be flowing in a southerly direction) at the western site boundary (SW2 upstream) and approximately 380 m west of the site (SW3 downstream). The exploratory hole location plan included within **Appendix 14M.ii (Document DCO 6.14M)** presents the locations of these samples.

- 14.4.25. It should be noted that the site GIR indicates the proposed scope of the investigation to comprise 3 No. surface water samples (SW1, SW2 and SW3). However, only 2 No. surface water samples were obtained (SW2 and SW3) as sampling at SW1 at the time of the visit was not possible due to the location being dry.
- 14.4.26. The chemical results from the surface water samples were assessed against published values from the Environment Agency (Environmental Quality Standards, EQS). Where assessment criteria was unavailable for certain chemical constituents, the UK Drinking Water Standards and World Health Organization Drinking Water Standards were used.
- 14.4.27. The surface water assessment detected a marginal exceedance in Naphthalene within the downstream sample obtained at SW3, as presented within the summary table below.

Table 14.7 Summary of Surface Water Chemical Exceedances

Determinant	Location	Contaminant	GAC for PAHs
		Concentration	(μg/l)
		(µg/l)	
Naphthalene	SW3 (downstream)	0.18	0.1

- 14.4.28. The concentration of Naphthalene within the upstream sample of SW2 measured <0.01 μg/l, which is below the laboratory limit of detection of <0.01 μg/l, and below the relevant generic assessment criteria of 0.1 μg/l. All naphthalene exceedances noted within the groundwater were recorded within the deeper groundwater body. Considering this, and the location of SW3 (approximately 380 m west of the site), it is likely that the exceedance is from an off-site source.
- 14.4.29. Additional surface water sampling and testing at the site was undertaken, with the findings presented within the EMG Phase 2 Technical Note: Surface Water Sampling, dated October 2024 (Appendix 14D Document DCO 6.14D). This involved the collection of 4 No. surface water samples (SW1 to SW4), with the locations presented on the surface water sampling location plan of the Technical Note, and summarised below:
 - SW01: Drainage ditch to the immediate north west of the site;
 - SW02: Drainage ditch located approximately 230 m west of site;
 - SW03: Drainage ditch located along the western order limit of the site; and
 - SW04: Drainage outfall located in the south eastern part of the site.
- 14.4.30. The chemical laboratory test results for all surface water samples collected indicated naphthalene concentrations of <0.01 µg/l, below the relevant GAC used in the GIR assessment and also below the laboratory limit of detection. Therefore, it is considered that the naphthalene exceedance recorded within the surface water sample obtained during the ground investigation was on isolated instance.
- 14.4.31. Considering the aforementioned evidence, the overall risk to surface waters is classified as low.

Ground Gas

14.4.32. Ground gas / vapour monitoring was undertaken at 15 No. locations across 3 No. monitoring return visits at the **EMG2 Main Site**. In accordance with BS8485:2015 A1:2019, a Characteristic Situation CS1 is considered appropriate for the site. Therefore, given the CS of the site, Table 4 of BS 8485:2015+A1:2019 indicates that there is no requirement for gas protection measures for both Type C and Type D structures on the **EMG2 Works**.

DCO Application - Highway Works

14.4.33. The findings of the two Preliminary Sources Study Reports (PSSRs) completed by BWB for the **Highway Works** part of the DCO Application (**Appendix 14E** and **14F – Documents DCO 6.14E and 6.14F)** have been reviewed and have informed the baseline conditions.

Junction 24 Improvements

- 14.4.34. The upgrade of Junction 24 of the M1 is proposed as part of the **Highway Works** to provide access and sufficient capacity to facilitate the development of the **EMG2 Works**.
- 14.4.35. The BWB PSSR (**Appendix 14E Document DCO 6.14E**) associated with the Junction 24 Improvements includes desk based information which has been reviewed to inform the baseline conditions and is summarised below.

History

- 14.4.36. This part of the **Highway Works** remained as largely undeveloped agricultural land with two roads running through the northern and southern vicinities, from the earliest available historical map of c.1883. By c.1921, air valves and rises (assumed to be associated with Kegworth R.D.O Reservoir) are mapped along the road in the northern vicinity and by c.1966, M1 construction had begun. Ashby Road is mapped in the southern area and is widened and labelled as A453 by c.1982.
- 14.4.37. A summary of the history of the area surrounding the **Highway Works**, specifically in regards to the J24 Improvements, is presented below:
 - From the earliest map of c.1883, Keyworth Village is mapped 750 m east and Lockington is mapped 500 m north west. A gravel pit and various small lakes are present 250 m north and, by c.1901, a covered reservoir is mapped 100 m south west.
 - By c.1912, the gravel pit previously identified to the north is no longer present, suggesting it had been infilled. Air valves, a washout chamber and sluice valves are mapped within this area.
 - By c.1966, the air valves and washout chamber are no longer mapped, and the M1 had been constructed over the same area.
 - By c. 1971, the covered reservoir is no longer present suggesting it had been infilled.
 - By c.1991, commercial / light industrial development had taken place within the surrounding vicinity, with a flood prevention lagoon mapped along the north eastern boundary.

By c.2024, East Midlands Airport is present 500 m south west and a services with a
petrol station is located 400 m south. The A50 eastbound is directly joined to the M1.

Anticipated Geology

- 14.4.38. Publicly available British Geological Survey (BGS) information indicated localised artificial deposits along the M1 corridor, suggesting areas which have been artificially raised and where the motorway has been constructed on an embankment.
- 14.4.39. BGS data indicates various superficial deposits in the north of the **Highway Works**, in regards to the J24 Improvements, and no superficial deposits to the south. These deposits include Wanlip Member, Head Deposits, Hemington Member, Holme Pierrepont Sand and Gravel Member and Eggington Common Sand and Gravel Member.
- 14.4.40. BGS data records various bedrock deposits across this part of the **Highway Works** comprising Gunthorpe Member (Siltstone and Mudstone), Diseworth Sandstone, Tarporley Siltstone Formation, Helsby Sandstone Formation, Edwalton Member, Branscombe Mudstone Formation and Arden Sandstone Formation.
- 14.4.41. BGS also indicates 2 No. faults through the centre of this part of the **Highway Works**, orientated approximately north west, south east.

Hydrogeology

14.4.42. **Table 14.8** below provides the hydrogeological Environment Agency (EA) classifications for each of the stratum mapped by BGS. This part of the **Highway Works** is not located within an EA designated Source Protection Zone (SPZ).

Table 14.8: EA Aquifer Designation

Stratum	EA Aquifer Designation		
Superficial Deposits			
Wanlip Member	Secondary A Aquifer		
Head Deposits	Undifferentiated Aquifer		
Hemington Member	Secondary A Aquifer		
Holme Pierrepont Sand and Gravel Member	Secondary A Aquifer		
Egginton Common Sand and Gravel	Secondary A Aquifer		
Member			
	Bedrock		
Gunthorpe Member (Siltstone and	Secondary B Aquifer		
Mudstone)			
Diseworth Sandstone	Secondary B Aquifer		
Tarporley Siltstone Formation	Secondary B Aquifer		
Helsby Sandstone Formation	Principal Aquifer		
Edwalton Member	Secondary B Aquifer		
Arden Sandstone Formation	Secondary A Aquifer		
Brancsombe Mudstone Formation	Secondary B Aquifer		

- 14.4.43. Part of the A50 Westbound is located within an active groundwater abstraction licence area, licenced to Tarmac Trading Limited. It is assumed that the associated groundwater abstraction is not utilised for potable water, due to the **Highway Works** not being located within a Source Protection Zone.
- 14.4.44. There are no discharge consents or pollution incidents relating to groundwater at the site of within 500 m.

Hydrology

- 14.4.45. There are no licensed abstraction, discharge consents or pollution incidents relating to surface on or within 500 m of this part of the **Highway Works**.
- 14.4.46. Tributaries of the Diseworth Brook flow near the A453 / Green Junction and 250 m west of the alternative principal access site. These tributaries flow into the Diseworth Brook southwest of the site.

Additional Environmental Information

- 14.4.47. This part of the **Highway Works** is not located within a coal mining reporting area, and there are no underground workings or mineral extractions recorded within the vicinity.
- 14.4.48. 1 No. Environment Agency (EA) landfill is located 399 m north, operated by Tarmac Aggregates Limited and is reported to receive Inert waste.
- 14.4.49. 1 No. waste exemption is located within this part of the **Highway Works**, at the A50 from M1 Junction 24 to B5010 roundabout. This is a 'using waste exemption' for the use of waste in construction.
- 14.4.50. The recorded landfills (>399 m north) are not considered to represent a significant ground gas risk at this part of the **Highway Works** due to distance, the recorded date of closure and the absence of enclosed spaces where gas could affect areceptor, combined with the fact that there are no sensitive receptors on highways. The waste exemptions are not considered to present a significant contamination risk due to the requirement of the exemptions for the handling of small quantities of waste (below waste permitting legislation) only.

Ground Investigations

- 14.4.51. The ground conditions at the J24 Improvements have been informed via the available existing ground investigations and reports, reviewed by BWB:
 - RSK Environment Ltd, Factual Ground Investigation Report, East Midlands Gateway Strategic Rail Freight Interchange, Zone 3, Major Trunk Road Improvements, Ref. 312494-03(00), dated December 2013; and
 - Amey Arup, Ground Investigation Report, Smart Motorways Programme M1, J23a-25, Ref. HA549342-AMAR-HGT-SWI-RP-CE-000002-Rev P0, dated February 2016.
- 14.4.52. Based on the aforementioned information, **Table 14.9** below provides a typical ground model for this part of the **Highway Works**.

Table 14.9: Junction 24 Improvements (Highway Works) Ground Model

Stratum	Top Depth (m bgl)		Base De	pth (m bgl)
	Min	Max	Min	Max
Topsoil	Ground Level		0.10	0.80
Made Ground	Ground Level		0.40	11.30
Fill / Possible Fill	Ground Level		0.70	1.80
Superficial Deposits	Ground Level		0.70	6.80
Mercia Mudstone (weathered)	Ground Level		Not Proven	
Mercia Mudstone	8.23	11.80	Not	Proven

Highway Works - Construction of Highway Infrastructure (Access to EMG2 Works)

- 14.4.53. The construction of highway infrastructure is proposed as part of the **Highway Works**, to provide access and sufficient capacity to facilitate the **EMG2 Project** development.
- 14.4.54. The associated BWB PSSR (**Appendix 14F Document DCO 6.14F**) includes desk based information pertaining to this part of the DCO Application. This information has been reviewed and is summarised below.

History

- 14.4.55. This part of the **Highway Works** remained as largely undeveloped agricultural land from the earliest available historical map of c.1884, until c.1921 where a pit containing an unspecified pump is shown on the planned northward extension of Hyam's Lane (later labelled as a pond by c.1962). An additional small pond is also mapped in the north east of the site by c.1962. This is thought to have been infilled by c.1971 due to the construction of the A5129 (later labelled A453) within that area. By c.2001, EMG1 access junction is mapped and by c.2024 the pond to the north of Hyam's Lane is not mapped and thus assumed to have been infilled.
- 14.4.56. The history of the area in relation to the highways infrastructure to facilitate access to the **EMG2 Main Site** is summarised below:
 - Much of the surrounding area comprised agricultural fields from c.1884 with the village of Diseworth located to the southeast, comprising a brick works (250 m south east) and graveyards (200 m and 300 m south east). An old gravel pit is mapped 50 m south east and the Diseworth Brook flows west to east, 300 m south.
 - By c.1962, 2 No. ponds are located 100 m south of Hyam's Lane and a disused airport is mapped directly north (later labelled as East Midlands Airport by c.1966).
 The M1 had been constructed to the east of the site by c. 1967.
 - By the 1980s, 2 No. electrical substations are present 200 and 400 m northeast of the A453/The Green Junction.
 - By the late 1990s, Finger Farm and Junction 23a had been constructed and resembles its present day configuration.
 - By c.2024, a petrol station is located 250 m south, comprising part of Donington Park Services.

Anticipated Geology

- 14.4.57. Published British Geological Survey (BGS) information indicates localised areas of Made Ground underlying sections of the Active Travel Link and A42 with a small area of Worked Ground just south east of the centre of the EMG2 Main Site.
- 14.4.58. Superficial deposits are mapped to comprise Glaciofluvial Deposits and Oadby Member within the southern **Highway Works**, with Alluvium and Head Deposits mapped in close proximity (underlying the A453/ The Green Junction).
- 14.4.59. Bedrock underlying the majority of these **Highway Works** is mapped to comprise the Gunthorpe Member and Diseworth Sandstone.
- 14.4.60. BGS mapping also indicates the presence of five faults located within this part of the **Highway Works.**

Hydrogeology

14.4.61. **Table 14.10** below provides the hydrogeological Environment Agency (EA) classifications for each of the stratum mapped by BGS. This part of the **Highway Works** is not located within an EA designated Source Protection Zone (SPZ).

Table 14.10: EA Aquifer Designation

Stratum	EA Aquifer Designation		
Superficial Deposits			
Glaciofluvial Deposits	Secondary A Aquifer		
Oadby Member	Undifferentiated Secondary Aquifer		
Head Deposits	Undifferentiated Secondary Aquifer		
Glaciolacustrine Deposits	Unproductive Stratum		
Bedrock			
Gunthorpe Member (Siltstone and	Secondary B Aquifer		
Mudstone)			
Diseworth Sandstone	Secondary B Aquifer		

Hydrology

- 14.4.62. There are no active abstraction licenses within a 2km radius of this part of the **Highway Works**.
- 14.4.63. There are 2 No. active discharge consents located 260 m west pertaining to trade discharges from East Midlands Airport into Whatton Brook and its tributaries.

Additional Environmental Information

- 14.4.64. 1 No. historical EA recorded landfill is located 160 m north west of Hyam's Lane, and is reported to have received inert, industrial commercial and household wastes between 1960 and 1970.
- 14.4.65. There are 79 No. waste exemptions within a 500 m radius, the majority of which are agricultural including the burning of waste in the open, storage of waste in a secure place, use of waste in construction, treatment of waste wood and waste plant matter by chipping and more.
- 14.4.66. The historical landfill is not considered to be a significant ground gas risk to this part of the **Highway Works**, due to distance, the recorded date of closure and the absence of enclosed spaces where gas could affect a sensitive receptor, combined with the fact that there are no sensitive receptors for highways. The waste exemptions are also not considered to be of significant contaminative potential, due to the reasons listed within Paragraph 14.4.50 above.

Ground Investigations

- 14.4.67. The ground conditions at this part of the **Highway Works** have been informed via the available existing ground investigations and reports, reviewed by BWB:
 - Structural Soils, EMG2 Phase 2 Factual Report on Ground Investigation (dated 2023); and
 - Geotechnics Ltd Ground Investigation at Land South of East Midlands Airport, Factual Report (dated 2024).
- 14.4.68. Based on the aforementioned information, **Tables 14.11** and **14.12** below provide a typical ground model for this part of the **Highway Works**.

Table 14.11: Central and Eastern Area

Stratum	Typical Profile	Description
Hardstanding	0.00 m to 0.30 m	N/A
Made Ground	0.30 m to 0.80 m	
Mercia Mudstone Group	0.80 m to 3.50 m	Brown or reddish brown silty
(Clay)		very sandy clays.
Weathered Mercia	3.50 m to 6.00 m (base not	Gravelly clayey sand and
Mudstone Group	proven)	slightly gravelly, sandy silty
(Siltstone)		clay with frequent lithorelicts.

Table 14.12: Western Area

Stratum	Typical Profile	Description
Hardstanding	0.00 m to 0.30 m	N/A
Made Ground	0.30 m to 0.80 m	
Oadby Member or	0.30 m to 0.90 m	Slightly sandy silty gravelly
Glaciofluvial Deposits		clay or slightly silty slightly
		gravelly sandy clay.
Mercia Mudstone Group	0.90 m to 5.80 m	Reddish brown silty clay.
(Clay)		
Weathered Mercia	5.80 m to 10.00 m	Gravelly clayey sand and
Mudstone Group		slightly gravelly silty clay
(Siltstone)		with frequent lithorelicts.

MCO Application - EMG1 Works

- 14.4.69. The findings of the RSK Environment Ltd ground investigation completed within the EMG1 Works and wider area between September 2013 and October 2013 have been reviewed to inform the baseline conditions (Appendix 14I:Factual Report and 14J:Interpretative Report Documents MCO 6.14I and 6.14J). It is acknowledged that these assessments were conducted in support of the previous EIA for EMG1. It is also acknowledged that various key guidance (LCRM, BS10175, BS5930) have undergone iterations of updates, however the core principles of the guidance remains consistent and given the site of the EMG1 Works have not been altered since the assessments, they are considered current and relevant.
- 14.4.70. The RSK intrusive investigation in relation to the wider EMG1 Scheme comprised:
 - 19 No. cable percussive boreholes;
 - 27No. trial pits, with the completion of 6No. soakaway tests in general accordance to BRE365;
 - 6No. rotary cored boreholes; and
 - installation of 25No. combined groundwater/gas monitoring wells and piezometers to varying depths to facilitate 4No. subsequent groundwater levels/ gas monitoring visits.
- 14.4.71. The following RSK exploratory hole locations are located within the **EMG1 Works** and within the close vicinity, and thus have informed the assessment of baseline conditions pertaining to the MCO Application. This includes the development area of Plot 16:
 - TP(S)304, TP(S)305, TP309, TP310, TP311, TP312, TP313, TP314, TP(S)352, TP(S)351; and
 - CP219, CP220, CP221 and CP222
- 14.4.72. The corresponding exploratory hole logs located within the **EMG1 Works** and within close vicinity indicate ground conditions to comprise:
 - Topsoil / Subsoil (from surface to depths of between 0.25 m bgl and 0.45 m bgl);

- Made Ground (from surface to a depth of 0.30 m bgl), encountered locally within CP222 located within the northernmost part of the proposed open land/landscaping area of the site;
- Egginton Common Sand and Gravel Member (encountered directly beneath the Topsoil / Subsoil extending to a depths of 2.50 m bgl to 4.60 m bgl) at CP2221 and TP310 located within the north eastern part of the proposed open land/landscaping area of the site;
- Head Deposits (encountered directly beneath the Topsoil / Subsoil extending to depths of between 0.45 m bgl and 1.80 m bgl)| at CP220, TP(S)304, TP309, TP313 and TP314 located within the south western part of the site;
- Thrussington Member (encountered directly beneath the Topsoil extending to depths
 of 1.80 m bgl) at CP219 located within Plot 16;
- Wanlip Member (encountered directly beneath the Topsoil / Subsoil / Made Ground and extending to depths of between 255 m bgl and 3.40 m bgl) at CP22, TP(S)305, TP(S)351 and TP(S)352 located within the north eastern part of the site;
- Taporley Siltstone Formation (encountered directly beneath Head Deposits / Subsoil / Thrussington member extending to depths of between 2.30 m bgl and 2.80 m bgl) at CP219, TP309, TP313 and TP314 located within Plot 16 and the southern part of the site.
- Edwalton Member (encountered directly beneath Head Deposits / Wanlip Member / Egginton Common Sand and Gravel Member / Taporley Siltstone Formation, extending to depths of between 2.50 m bgl and 10.50 m bgl) at CP220, CP221, CP222, CP219, TP(S)304, and TP311 located within Plot 16 and the northern part of the site; and
- Arden Sandstone Formation (encountered directly beneath the Edwalton Member extending to 10.94 m bgl) at CP221 located within the north eastern part of the site.
- 14.4.73. No visual or olfactory evidence of evidence of soil or groundwater contamination was recorded during the site investigation.
- 14.4.74. Groundwater strikes were recorded within TP(S)351 at a depth of 2.35 m bgl (36.19 m AOD) within the granular horizons of the Wanlip Member, and within CP221 and CP222 at depths of 9.65 m bgl (32.01 m AOD) and 6.40 m bgl (30.65 m AOD), respectively, within the Edwalton Member.
- 14.4.75. Four rounds of subsequent groundwater monitoring were completed by RSK on separate occasions over a five week period, between the 16th October 2013 and 11th November 2013 (including one round of groundwater sampling). The results of the groundwater monitoring at CP219 to CP222 indicate a groundwater level of between 2.08 m bgl (41.54 m AOD) at CP220 and 7.34 m bgl (47.12 m AOD) at CP219 within the Edwalton Member.
- 14.4.76. **Table 14.13** below summarises the geo-environmental soil and groundwater laboratory tests which have been completed across the entirety of the site, including the exploratory positions listed within Paragraph 14.4.71:

Table 14.13: Geo-Environmental Testing: EMG1 Works – MCO Application

Geo-Environmental Test	Number of Soil Tests	Number of Groundwater
OCO-LIIVII OIIIIICIII ai Test	Humber of John Tests	Tests
pH, Arsenic, Cadmium,	10	-
Copper, Chromium, Chromium	(4 No. SS, 1 No. MG, 1	
(hexavalent), Lead, Mercury,	No. HD, 1 No. ECSG, 1	
Nickel, Selenium, Zinc	No. WM, 3 No. TSF)	
pH, Redox potential, Electrical	-	7
conductivity, dissolved oxygen,		
hardness, ammoniacal		
nitrogen, Phenols, Arsenic,		
Cadmium, Copper, Chromium,		
Chromium (hexavalent), Lead,		
Mercury, Nickel, Selenium,		
Zinc		
Total Organic Carbon (TOC)	8	-
	(1 No SS, 1 No. MG, 1	
	No. HD, 1 No. ECSG, 1	
	No. WM, 3 No. TSF)	
Polycyclic Aromatic	11	7
Hydrocarbons (PAH) -	(4 No. SS, 1 No. MG, 1	
Speciated (EPA 16)	No. HD, 1 No. ECSG, 1	
	No. WM, 3 No. TSF)	
Semi Volatile Organic	-	7
Compounds (SVOCs) and		
Volatile Organic Compounds		
(VOCs)		
Total Petroleum Hydrocarbons	11	7
Criteria Working Group (TPH	(4 No. SS, 1 No. MG, 1	
CWG) + BTEX and MTBE	No. HD, 1 No. ECSG, 1	
	No. WM, 3 No. TSF)	
Triazine Herbicides	4	-
	(4 No. SS)	
Pesticides	4	-
	(4 No. SS)	
Asbestos Screen (with	3	-
quantification, if required)	(2 No. SS, 1 No. HD)	

Notes:

SS: Subsoil, **MG**: Made Ground, **HD**: Head Deposits, **ECSG**: Egginton Common Sand and Gravel, **WM**: Wanlip Member, **TSF**: Tarporley Siltstone Formation

Risks to Human Health

14.4.77. The laboratory soil chemical results pertaining to the site have been compared directly to the appropriate GAC for each contaminant, based upon a conservative Soil Organic Matter (SOM) of 1%.

- 14.4.78. Results indicate that all concentrations of contaminants analysed were below the commercial end use assessment criteria and therefore the overall risks to future end users is considered low.
- 14.4.79. Additionally, no visual evidence of Asbestos Containing Material (ACM) was noted during the investigation, and ACM was not identified in any of the 3 No. soil samples submitted to the laboratory for asbestos screening.
- 14.4.80. Soil concentrations recorded across the sitewere also compared against UKWIR "Guidance for the selection of Water Supply Pipes to be used in Brownfield Sites (Ref. 10/WM/03/21". Results of the assessment indicate a relevant linkage is unlikely to exist associated with organic contaminants and therefore Polyethylene (PE) and/or Polyvinyl Chloride (PVC) water supply pipes are expected to be suitable for use.

Risks to Controlled Waters

- 14.4.81. Seven groundwater samples obtained from the groundwater monitoring rounds completed were submitted to the laboratory for the geo-environmental testing listed within **Table 14.13**.
- 14.4.82. The chemical results from the groundwater laboratory tests were assessed against the UK Drinking Water Standards and Freshwater Environmental Quality Standards (EQS), or where unavailable, the World Health Organization Drinking Water Standards to assess the risk to the wider Secondary Aquifer body.
- 14.4.83. The assessment concluded that, for the groundwater samples obtained from the site, the analytical results are below the relevant GAC.
- 14.4.84. One sample (CP210) located outside of the site, to the immediate north of East Midlands Airport, returned a phenol concentration of 0.05 mg/l, which exceeds the Freshwater EQS of 0.03 mg/l. This was not reflected within the samples obtained from the site.

Ground Gas

14.4.85. Four rounds of ground gas monitoring were also completed by RSK Environment Ltd over the period of five weeks, from 16th October 2013 to 11th November 2013. Assessment of the screening results, in accordance with BS8485:2015+A1:2019, classifies the whole of **EMG1** Works (including Plot 16) as a Characteristic Situation (CS) 2 - Low Risk. Therefore, in accordance with Table 4 of the aforementioned British Standard reference, a gas resistant membrane is recommended.

Key Receptors

- 14.4.86. Sensitive receptors to be considered within the Ground Conditions and Contamination assessment include the below:
 - Future site users Commercial users in the form of on-site staff, visitors and
 occasional building maintenance workers. These users may be exposed via direct
 contact, ingestion and / or inhalation of contaminated soils (in the presence of soft
 landscaping), ingress of contaminants into conduits contaminating drinking water
 supply pipes, and the inhalation of accumulated soil ground gas or vapours. Future

- site users are considered to be of moderate sensitivity, due to the anticipated length time they are likely to spend at the **EMG2 Project** and due to the proposed well-ventilated nature of the Type D Buildings.
- Construction / maintenance workers These receptors may be exposed to potential
 contamination within soils and groundwater during the ground works for the
 proposed development. Construction workers are considered to be of moderate
 sensitivity, although this is thought to be reduced to moderate/ low sensitivity due to
 the assumption that health and safety risk assessment and mitigation including basic
 hygiene and the correct use of personal protective equipment (PPE) / respiratory
 protective equipment (RPE) will be applied by all competent contractors.
- Off-site users (East Midlands Airport, Lockington, Hemington, Castle Donington and Public) – Potential contamination exposure to surrounding off-site users. Much of the surrounding land is either occupied by commercial land use (such as Donington Park Services), or vacant land, associated with low sensitivity.
- Off-site users (residential) Immediate High_sensitivity residential receptors are located along Grimes Gate and Cheslyn Crescent in Diseworth.
- Controlled Waters, Aquifers EA designated aquifers identified to be present beneath the EMG2 Project, including Secondary A Aquifers, Secondary Undifferentiated Aquifers, Secondary B Aquifers, and a Principal Aquifer associated with the Helsby Sandstone Formation located within the Highway Works. The Secondary Aquifers are considered to be of moderate sensitivity and the Principal Aquifer is considered to be of high sensitivity. However, no part of the EMG2 Project is located within an Environment Agency designated Source Protection Zone (SPZ).
- Controlled waters, surface water nearby surface water courses / drainage ditches including the inland rivers identified south of the EMG2 Works (Diseworth Brook 320m south and Long Whatton Brook 500m south east of the site) and 2 No. drainage ditches which converge in the south eastern corner of the EMG2 Works. The regional deeper groundwater flow direction is towards the south. As such, the surface water receptors are largely associated with the ponds identified on the EMG2 Works, the aforementioned drainage ditch and tributaries of the Diseworth Brook. Sensitivity is considered to be moderate due to the GIR proving that the drainage ditches are in hydraulic connectivity with the shallow groundwater body, and thus it is considered that there is a pathway for groundwater contamination (PAH exceedances) identified to enter the two nearby watercourses. However, the completeness of this pathway is considered unlikely due to the watercourses being located >300 m from the EMG2 Works and due to the fact that the PAH contamination was generally identified within the deeper groundwater body, with the exception of a localised pyrene exceedance in the shallow groundwater at CP27.
- On-site and off-site buildings and associated infrastructure could potentially be at risk from ground gas migration, particularly via preferential pathways, aggressive ground / groundwater conditions and contaminants (such as hydrocarbons) with the potential to permeate through underground services, such as water supply pipes. The receptor is considered to be of low sensitivity.
- Plants and vegetation primarily at risk from phytotoxic contaminants such as copper, nickel and zinc. The sensitivity to proposed on-site plants and vegetation is

considered to be low, due to the GIRs revealing no soil exceedances of the relevant GAC for these phytotoxic contaminants.

14.4.87. The sensitivity of identified receptors is summarised in **Table 14.14** below:

Table 14.14: Receptor Sensitivity

Receptor	Sensitivity
Future site users – commercial	Moderate
Construction / maintenance workers	Moderate
Off-site users – residential	High
Off-site users – commercial	Low
Controlled Waters – Secondary Aquifers	Moderate
Controlled Waters - Principal Aquifer	High
Controlled Waters – surface waters	Moderate
On-site and off-site buildings and infrastructure	Low
Plants and vegetation	Low

Risks to Human Health - DCO Application

- 14.4.88. The findings of the ground investigation and subsequent geo-environmental assessments at the **EMG2 Works** indicates no exceedances of the site specific criteria or commercial end use generic assessment criteria (GAC) with respect to human health. Aside from CP27 (where an 'iridescent sheen and moderate to strong hydrocarbon odour' was noted within the Made Ground), no visual or olfactory evidence of contamination was observed.
- 14.4.89. The **Highways Work** is considered to be of lowest sensitivity due to proposed end use. BWB PSSRs (**Appendix 14E** and **14F Document DCO 6.14E** and **6.14F**) do not indicate any known sources of contamination.
- 14.4.90. Therefore, the overall risk to site end users from direct contact with contaminated soils associated with the DCO Application is considered to be low.

Risks to Drinking Water Supply Pipes - DCO Application

14.4.91. The findings of the ground investigation and geo-environmental assessment at the **EMG2**Works recorded 2 No. exceedances of the UKWIR threshold for polyethylene pipe and 1

No. exceedance of the threshold for the polyvinyl chloride pipe. Although these exceedances were noted, the use of upgraded drinking water supply pipes at the **EMG2 Works** is not considered necessary (Paragraph 14.4.14) and therefore the overall risk is considered to be low. A WIR assessment may be required along the proposed drinking water pipe route to demonstrate material suitability, or the use of a barrier pipe may be considered to negate the need for further testing.

Risks to Controlled Waters - DCO Application

Groundwater

- 14.4.92. Within the EMG2 Works, the groundwater laboratory results were generally recorded as below the generic assessment criteria (UKDWS or WHO drinking water standards), with a small number of PAH exceedances noted within the northern and southern areas, recorded within the deeper groundwater. The PAH exceedances were noted to be localised within the deeper groundwater due to the fact that they were surrounded by non-detects. Greater PAH exceedances were recorded in the northern part of the EMG2 Works compared to the southern part. Due to the lack of PAH contamination within soil samples scheduled, it is considered that this PAH is likely to have leached into the groundwater from an off-site source. This, combined with the absence of groundwater abstraction points within a 1 km radius of the EMG2 Works, results in an overall low risk to groundwater.
- 14.4.93. The BWB PSSRs do not identify any known sources of contamination within the area of the **Highway Works**. Therefore, the contaminative risk, including the risk to groundwater, is considered low.

Surface Water

- 14.4.94. 2 No. surface water samples were obtained during the **EMG2 Works** ground investigation, and were scheduled for geo-environmental laboratory analysis. The results of such analysis revealed 1 No. marginal exceedance of Naphthalene within the downstream sample obtained from SW3 when compared to the relevant generic assessment criteria. This sample is not located within the EMG2 Works (some 380 m west). All naphthalene exceedances noted within the groundwater were recorded within the deeper groundwater body. Additional surface water sampling completed in 2024 (**Appendix 14D Document DCO 6.14D**) involved the collection of a further 4 No. surface water samples and geo-environmental laboratory analysis. Naphthalene exceedances were not recorded within any of these surface water samples. Considering this, it is likely that the initial exceedance recorded was from an off-site source. Therefore, the overall risk to surface water at the **EMG2 Works** is considered to be low.
- 14.4.95. The PSSR for the highways works did not identify potential sources capable of presenting an unacceptable risk to surface waters and as such sampling and testing was not conducted. Risks from the **Highway Works** and proposed development are considered low.

Risks from Ground Gas - DCO Application

14.4.96. Based on the maximum flow rate and maximum concentrations recorded during the ground gas monitoring at the **EMG2 Works**, a gas screening value of 0.2025 l/hr was recorded at BH04, based on carbon dioxide concentrations. Review of this data indicates that the elevated flow was not representative of the overall **EMG2 Works** conditions, as it was only recorded on one occasion in one deep borehole. Also, soil organic matter was generally recorded as low and the Made Ground thicknesses encountered were generally less than 1.0 m (with the exception of CP27). Therefore, the **EMG2 Works** is considered representative of CS1 conditions, and thus, it is unlikely that a potentially complete contaminant linkage associated with ground gas exists at the **EMG2 Works**.

14.4.97. The BWB PSSRs for the **Highway Works** indicates the historical presence of landfills with possible ground gas generation potential. However, due to the distance, the recorded dates of closure and the absence of enclosed spaces where gas could affect a sensitive receptor, the risks associated with ground gas at the **Highway Works** is considered to be low.

Risks to Human Health - MCO Application

14.4.98. The findings of the ground investigation and subsequent geo-environmental assessments at the EMG1 Works indicates no exceedances of the site specific criteria or commercial / industrial generic assessment criteria (GAC) with respect to human health. Therefore, the overall risk to human health from direct contact with contaminated soils associated with the MCO Application is considered to be low.

Risks to Drinking Water Supply Pipes - MCO Application

- 14.4.99. The findings of the ground investigation and geo-environmental assessment for the **EMG1 Works** concludes that all soil chemical results are below the UKWIR guidance, and therefore a relevant contaminant linkage is unlikely to exist associated with organic contaminants permeating drinking water supply pipes, corresponding to a low risk.
- 14.4.100. For the proposed development of the EMG1 Works, the local water company should be contacted to agree the chosen pipe material suitability, across all three components, where necessary.

Risks to Controlled Waters - MCO Application

Groundwater

14.4.101. The findings of the geo-environmental assessment pertaining to the EMG1 Works indicated that the groundwater laboratory results are generally below the controlled waters generic assessment criteria (UK DWS / EQS, or best equivalent). One exceedance of the freshwater EQS was noted for phenols (CP210), however this is located outside of the EMG1 Works and there is no source of phenols on site. Therefore, the overall risk to groundwater associated with the MCO Application is considered to be low.

Surface Water

14.4.102. Surface water sampling was not completed as part of the **EMG1 Works** ground investigation. However, considering that no significant Made Ground or contamination was encountered, it can be concluded that the potential risks to surface waters associated with the MCO Application are low.

Risks from Ground Gas - MCO Application

14.4.103. Based on the maximum flow rate and maximum concentrations recorded during the RSK Environment Ltd ground gas monitoring at the EMG1 Works, gas screening values of 0.0l/hr were concluded for methane and 0.10l/hr for carbon dioxide. In accordance with BS8485:2015+A1:2019, these GSVs correspond to CS2 conditions. Table 4 of the aforementioned British Standard recommends that a gas resistant membrane is utilised in the development.

Risks to Plants and Vegetation - DCO Application

14.4.104. The risks to the proposed soft landscaping at the **EMG2 Works** (for example, DCO Works No. 21 – Community Park – of the Components Plan **Document DCO 2.7**) from phytotoxic contaminants (copper, nickel, boron and zinc) is concluded as low, with a potentially complete contaminant linkage unlikely to exist.

Risks to Plants and Vegetation – MCO Application

14.4.105. The risks to the proposed soft landscaping at the **EMG1 Works** (for example, MCO Works Nos. 3A, 5A & 6A – EMG1 Works - of the Components Plan **Document MCO 2.7)** from phytotoxic contaminants (copper, nickel, boron and zinc) is concluded as low, with a potentially complete contaminant linkage unlikely to exist.

Future Baseline Conditions

14.4.106. With the presumption that there is no future development on the land identified for the EMG2 Works, EMG1 Works, Highway Works (EMG2 Project) or surrounding area that may introduce new sources of potential contaminants, it is expected that there would be no change in the current site baseline conditions at the time of preparing this ES Chapter. This, however, assumes that the risks from any additional potential contaminant sources are appropriately managed and mitigated adhering to the pertinent legislation.

14.5. Potential Impacts

- 14.5.1. This section provides an assessment of the proposed changes to the ground conditions throughout the development project, which are likely to generate effect.
- 14.5.2. **Chapter 1: Introduction (Document DCO 6.1/MCO 6.1)** of this ES explains the definitions associated with short term, medium term and long term duration of impacts. This is taken into consideration in the below sections. The construction phase is anticipated to be of short to medium term duration and the operational phase is considered to be of long term duration.

Embedded Mitigation – DCO Application

- 14.5.3. The assessment in this Chapter takes into account 'embedded' mitigation measures and standard construction practises, such that potential adverse impacts to ground conditions (resulting in baseline deviation) can be mitigated. Details of the embedded mitigation measures for the EMG2 Works and Highway Works (DCO Application) are discussed within the Construction Environmental Management Plan (CEMP) Document DCO 6.3A.
- 14.5.4. The following embedded mitigation measures of relevance to ground conditions will be implemented during the construction phase of the **EMG2 Works** and **Highway Works**:
 - A Construction Environmental Management Plan (CEMP) (Document DCO 6.3A)
 has been prepared as part of the DCO Application to manage the environmental
 impacts during the construction phase of the EMG2 Works and Highway Works.
 This includes an Outline Silt Management Plan (SMP) which will be refined in
 advance of construction.

- Where pre-existing contamination has been found to exist. Contractors will be required, in accordance with Requirement 22, to undertake remediation measures identified in the geo-environmental assessment, investigations and reports in a suitable manor. All measures must be agreed with the Environment Agency (EA) before the implementation of any measures and verification reports shall be prepared and issued to the EA on completion of the remediation measures.
- A UXO risk assessment will be undertaken before any intrusive works commence.
- In the event that suspected contaminated material is uncovered during the works, an
 appropriate area will be protected, all works will be suspended and a suitably qualified
 person shall be engaged to investigate and develop a suitable strategy for dealing
 with any contaminated material.
- The Contractor should plan and execute the work to ensure that hazardous or polluting substances do not cause harm to underlying aquifers, surface water systems, landscaping and associated ecology, in accordance with the CEMP (Document DCO 6.3A).
- At the commencement of any component of earthworks, the necessary permit drainage basins for that component will be constructed and outfalls into the existing water courses will be provided, in accordance with the drainage strategy (Chapter 13: Flood Risk and Drainage Document DCO 6.13). Additional settlement and control ponds will be provided as necessary during a component to prevent potential pollution entering the existing watercourse.
- All Contractors shall adopt water pollution prevention procedures in line with good practice during the earthworks, in accordance with the SMP, appended to the CEMP (Document DCO 6.3A).
- Regular monitoring of the downstream water quality will be undertaken during the
 construction phase to ensure that the sediment and pollution control measures are
 working effectively. Testing parameters shall be agreed with the Environment Agency
 or lead local flood authority as appropriate ahead of collection of baseline test data.
- Environment Agency Guidance for Pollution Prevention (GPPs) will be adhered to at all times to reduce the chance of chemical skills and other pollution events. Relevant spill kits will be kept on site for the rapid treatment of any spillages. Exclusion fencing will be established along the routes of watercourses and particular care taken in terms of movement of machinery and storage of materials in proximity to these features.

Embedded Mitigation – MCO Application

14.5.5. The embedded mitigation measures pertaining to the **EMG1 Works** of the MCO Application will comprise those which are listed within the framework CEMP that was previously approved in accordance with Requirement 11 of the EMG1 DCO.

DCO Application

Construction Phase

14.5.6. The potential effects of construction at the EMG2 Works and Highway Works pertaining to the DCO Application which may result in a change to the previously identified baseline conditions are listed below. Consideration of these effects with reference to the identified receptors is also discussed.

Removal of Topsoil and Shallow Soils

The EMG2 Works will be subject to a cut and fill procedure to form a series of development platforms as shown at Appendix 14M (Document DCO 6.14M). EMG2 Works plateau level plans indicate the creation of several plateau levels across the site, ranging from 66.750 m AOD in the far southern area to 89.000 m AOD in the far north eastern area. This cut will include the stripping of site topsoil and shallow soils, thus disturbing the natural in-situ strata.

Alterations to Soil and Groundwater Quality

- Construction plant and associated activities may affect the site ground conditions through contaminant introduction or mobilisation via spillages or leakages, for example, from lubricants, oils, fuel and uncured concrete.
- 14.5.7. The below section considers the identified potential effects as part of the DCO Application during construction with reference to the site receptors.
 - Construction / maintenance workers The potential for contamination to be present
 on the EMG2 Works and Highway Works is considered to be low, and the likely
 duration of construction is considered short to medium. This, combined with the
 moderate sensitivity of construction / maintenance workers and the Negligible
 magnitude of impact results in an overall Negligible significance of effect. This does
 not consider any potential contamination which has not been identified to date at the
 site.
 - Off-site users (Residential) It is unlikely that there are any potentially complete
 human health contaminant linkages at the EMG2 Works and Highway Works and
 therefore the magnitude of impact is considered Negligible. Although off-site
 residential receptors are considered to be of high sensitivity, the distance of these
 receptors to the EMG2 Works and Highway Works (associated with the risk to
 human health from inhalation pathways) results in an overall Negligible significance.
 - Off-site users Commercial (East Midlands Airport, Lockington, Hemington) It is
 unlikely that there are any potentially complete human health contaminant linkages
 at the site and therefore the magnitude of impact is considered Negligible. This,
 combined with the low sensitivity of off-site commercial users, and the distances of
 the surrounding site users to the EMG2 Works and Highways Works (associated
 with the risk to human health from inhalation pathways), results in an overall
 Negligible significance.

- Controlled waters, surface waters 1 No. Naphthalene exceedance was noted within a surface water sample (SW3) obtained from approximately 380 m west of the EMG2 Works. Provided all Naphthalene exceedances noted within the groundwater were recorded within the deeper groundwater body and that no exceedances were noted within the upstream sample of SW2, or within the supplementary surface water samples obtained within 2024, the magnitude of impact is likely to be Negligible. It is considered that the surface water exceedance is likely from an off-site source. This, combined with the moderate sensitivity of surface waters and the short to medium duration of the construction phase, results in a Negligible significance of effect.
- Controlled Waters Principal Aquifer The northern part of the Junction 24 improvement Highway Works is underlain by a Principal Aquifer supported by the Helsby Sandstone Formation, which is considered to be of high sensitivity. However, according to the ground conditions presented within the BWB PSSR (Table 14.9), this sandstone stratum is likely to be overlain by at least 10 m of low permeability Mercia Mudstone, which is anticipated to act as an aquitard. Therefore, considering this, the effect of construction to groundwater within the Principal Aquifer is likely to be Negligible. It should be noted that Paragraph 3.3 of Chapter 3: Project Description (Document DCO 6.3) states that the development 'may include piled foundations for the bridge works as part of the J24 Improvements'. Subject to the final foundation design, specific locations of the piles and ground conditions at those locations, a Foundation Works Risk Assessment (FWRA) may be required if the foundations are piled directly into the Principal Aquifer.
- Controlled waters, Secondary Aquifers Considering the PAH exceedances within the deeper groundwater samples obtained from the EMG2 Works were noted to decrease in concentration from the northern extent to the southern extent, it is likely that the impact is not mobile (due to low permeability on site). Only 1 No. PAH exceedance was noted within the shallow groundwater (within the Made Ground of CP27), which is considered to be localised. Therefore, considering this, the moderate sensitivity of non-potable aquifers and the short to medium duration of the construction phase, the potential significance of effect of construction to groundwater is considered to be Negligible.
- 14.5.8. If any unforeseen contamination is encountered during the construction phase, requirement 22 of the draft DCO necessitates this to be investigated with a risk assessment approach and, if required, remediation to be undertaken in consultation with the Local Planning Authority.

Operational Phase

14.5.9. The **Highway Works** and the majority of the **EMG2 Works** (apart from the Community Park) will include substantial areas of impermeable hardstanding, consisting of buildings, roads, staff amenity space and off and on plot pathways. Therefore, any potential effects to the previously discussed baseline conditions which may have occurred during the construction phase should have been mitigated via a staged process ground investigation and risk assessment, with any necessary remedial measures required to have been implemented at the site prior to its operation.

- 14.5.10. There is not expected to be any considerable change to the levels (e.g. requiring substantial construction / breaking of ground) across the EMG2 Works or Highway Works during the operational phase, and the risk of soil and groundwater contamination through contaminant introduction or mobilisation via spillages or leakages from machinery is expected to be significantly decreased.
- 14.5.11. The potential effects of operation at the **EMG2 Works** and **Highway Works** pertaining to the DCO Application are listed below:
 - The introduction of EMG2 Works end users to the development, within the buildings and outdoor landscaped space. This may increase the likelihood of contact with potentially contaminated soils, groundwater, and/or surface waters through ingestion, dust inhalation and dermal contact. Albeit, the likelihood of a potentially complete contaminant pathway is considered to be low. The introduction of end users to the Highway Works is considered to be very low sensitivity due to the limited end users of maintenance workers and very occasional use of laybys by broken down vehicle users.
 - The introduction of soft landscaped areas comprising plants and vegetation, at the EMG2 Works (particularly the Community Park DCO Works No. 21 on Components Plan (Document DCO 2.7) which may result in the uptake of phytotoxic contaminants.
 - The introduction of the buildings to the **EMG2 Works**, potentially resulting in ground gas accumulation and (worst case) asphyxiation.
 - The risk to future building maintenance workers where breaking ground / excavations are required, increasing the likelihood of coming into contact with contaminated soils at the site.
- 14.5.12. The following section considers the identified potential effects as part of the DCO Application during operation with reference to the site receptors:
 - Future site users / maintenance workers the findings of the ground investigation and subsequent geo-environmental assessments for the EMG2 Works have concluded that a potentially complete contaminant linkage with reference to human health is unlikely. The BWB PSSRs for the Highway Works have not identified any potential sources of contamination. Therefore, the magnitude of impact is considered Negligible. The Negligible magnitude of impact combined with the moderate sensitivity of future commercial users results in what is considered to be of Negligible significance.
 - Off-site users considering the low potential for contamination across the EMG2
 Works and Highway Works and the limited dust generation potential, the
 magnitude of impact is considered Negligible. This, combined with low / high (offsite commercial users / residential users) sensitivity of users, with the consideration
 to pathway distance, results in what is considered to be of Negligible significance.
 - Controlled waters it is considered that the overall risk to groundwater and surrounding surface waters at the site will not change following the proposed development of the EMG2 Works and Highway Works, and therefore the

magnitude of impact is considered Negligible. This, combined with the moderate / low sensitivity of controlled waters, relating to non-potable water aquifers and surface waters, respectively, results in an overall Negligible significance.

MCO Application

Construction Phase

14.5.13. The potential effects of construction at the **EMG1 Works** pertaining to the MCO Application (including the additional warehousing development on Plot 16) which may result in change to the previously identified baseline conditions are broadly similar to those listed above:

Removal of Topsoil and Shallow Soils

It is anticipated that earthworks will be required to form the required levels across
the EMG1 Works. Therefore, it is assumed that there will be a topsoil strip, and
potentially shallow soil excavation, to facilitate the development, thus disturbing the
natural strata.

Alterations to Soil and Groundwater Quality

- Construction plants and associated activities may affect the site ground conditions through contaminant introduction or mobilisation via spillages or leakages, for example, from lubricants, oils, fuel and uncured concrete.
- 14.5.14. The below section considers the identified potential effects as part of the MCO Application during construction with reference to the **EMG1 Works** receptors.
 - Construction / maintenance workers The potential for contamination to be present
 on the EMG1 Works is considered to be low, and the likely duration of construction
 is considered short to medium. This, combined with the moderate sensitivity of
 construction / maintenance workers and the Negligible magnitude of impact results
 in an overall Negligible significance of effect. This does not consider any potential
 contamination which has not been identified to date at the site.
 - Off-site users Commercial (East Midlands Airport, Lockington, Hemington) It is
 unlikely that there are any potentially complete human health contaminant linkages
 at the site and therefore the magnitude of impact is considered Negligible. Although
 the commercial off site users are located within a closer distance to the EMG1
 Works, the low sensitivity of the receptor (associated with the risk to human health
 from inhalation pathways throughout construction) results in an overall Negligible
 significance.
 - Controlled Waters, Secondary Aquifers The geo-environmental laboratory results pertaining to the groundwater samples obtained from EMG1 Works during the ground investigation did not reveal any exceedances of the relevant generic assessment criteria (DWS and EQS). One sample (CP210) returned a minor exceedance of the freshwater EQS threshold associated with phenol concentration. However, this sample is located outside of the EMG1 Works and there are no known sources of phenols on site. Therefore, considering this, the moderate sensitivity of

non-potable aquifers and the short to medium duration of the construction phase, the potential significance of effect of construction to groundwater is considered to be Negligible.

14.5.15. Similar to the position noted within Paragraph 14.5.8 above, If any significant contamination is encountered during the construction phase, Requirement 24 of the EMG1 DCO necessitates this to be investigated with a risk assessment approach and, if required, remediation to be undertaken in consultation with the Local Planning Authority.

Operational Phase

- 14.5.16. Operational Phase The majority of the EMG1 Works (apart from the proposed area of open land / landscaping surrounding the warehouse at Plot 16) will be covered with impermeable hardstanding, including the warehouse space, car parking, service yards, amenity buildings, roads, paths utility and infrastructure. Therefore, any potential effects to the previously established baseline conditions which may have occurred during the construction phase should have been mitigated via a staged process ground investigation and risk assessment, with any necessary remedial measures required to have been implemented at the site prior to its operation.
- 14.5.17. There is not expected to be any considerable change to the levels (e.g. requiring substantial construction / breaking of ground) across the EMG1 Works during the operational phase, and the risk of soil and groundwater contamination through contaminant introduction or mobilisation via spillages or leakages from machinery is expected to be significantly decreased.
- 14.5.18. The potential effects of operation at the **EMG 1 Works** pertaining to the MCO Application are listed below:
 - Introduction of EMG1 Works end users to the development, within the indoor warehouse area and outdoor landscaped space pertaining to Plot 16. This may increase the likelihood of a human health linkage with potentially contaminated soils, groundwater and / or surface waters through dermal contact, ingestion and dust inhalation. However, this is considered Negligible at this stage, due to fact that the ground investigation did not reveal any significant contamination. The introduction of site end users to the remaining areas of the EMG1 Works (including increasing the permitted height of cranes at the rail-freight terminal, improvements to public transport interchange and site management building) is considered to be of lower sensitivity due to the limited anticipated impact on ground conditions.
 - The introduction of soft landscaped areas comprising plants and vegetation surrounding Plot 16 of the EMG1 Works, which may result in the uptake of phytotoxic contaminants.
 - The introduction of the warehouse building to Plot 16 of the EMG1 Works, potentially resulting in ground gas accumulation and (worse case) asphyxiation;
 - The risk to future building maintenance workers where breaking ground / excavations are required, increasing the likelihood of coming into contact with contaminated soils at the site.

The following section considers the identified potential effects as part of the MCO Application operation with reference to the site receptors:

- Future site users / maintenance workers the findings of the ground investigation and subsequent geo-environmental assessments for the EMG1 Works concluded that a potentially complete contaminant linkage with reference to human health is unlikely. The ground gas monitoring completed as part of the ground investigation concluded Characteristic Situation (CS) 2, as defined in BS8485, requiring a gas resistant membrane within the warehouse area of Plot 16. Provided the remediation measures are confirmed and implemented, the magnitude of impact is considered Negligible. The Negligible magnitude of impact combined with the moderate sensitivity of future commercial site users results in Negligible significance.
- Off-site users considering the low potential for contamination across the EMG1
 Works, the magnitude of impact is considered to be Negligible. This, combined with
 the low (off site commercial users) to high (off site residential users) sensitivity of
 users, with the consideration of pathway distance, is considered to be of Negligible
 significance.
- Controlled waters it is considered that the overall risk to groundwater and surrounding surface waters will not change following development, and throughout the operational phase of the EMG1 Works, and therefore the magnitude is considered Negligible. This, combined with the moderate / low sensitivity of controlled waters relating to non-potable aquifers (Secondary A, Secondary B, Undifferentiated) beneath EMG1 Works, results in an overall Negligible significance.

EMG2 Project

14.5.19. The potential effects of the DCO and MCO Applications have been assessed in the preceding section and in **Table 14.15** attached at the end of this Chapter. The combination of the **EMG2 Project** is considered to have no greater effect than the associated components, given the effects are negligible (**EMG1 Works**, **EMG2 Works** and **Highway Works**) individually.

14.6. Mitigation Measures

14.6.1. This section of the ground conditions chapter provides a summary of the mitigation measures proposed to be implemented during the construction and operational phases of the proposed **EMG2 Project** development.

Construction Phase – DCO Application

- 14.6.2. Based on the intrusive information and risk assessments, the following mitigation measures in the construction phase include:
 - General construction phase mitigation, to mitigate the potential exposure to construction workers during the progression of the development, including the development of and adherence to a site health and safety plan, pre-approved RAMS,

personal hygiene and welfare, correct PPE/RPE, decontamination measures if necessary, the safe and recorded storage of fuels/oils and any other potentially contaminative liquids, and regular cleaning of all site roads. These measures are detailed within the Construction Environmental Management Plan (CEMP) prepared for the **EMG2 Works** and **Highway Works** (DCO Application), provided as **Document DCO 6.3A**. Phase specific construction environmental management plan(s) (P-CEMP) will be drafted in accordance with the principles set out in the CEMP and submitted as per draft DCO Requirement 11;

- The CEMP also includes a Silt Management Plan which is intended to limit the volume of potential silt laden run-off throughout the Earthworks. This includes the management of machinery and material movement (e.g. designated machine and dumper tracking routes), control of stockpiled materials (e.g. maximum height of 2.0 m, stockpiles must be sufficiently compacted and should be temporarily covered with the use of a seal), the use of temporary plot drainage (temporary settling basins with silt management deployment techniques) and the completion of monitoring procedures and records.
- Selection of appropriate materials for buried water supply pipes across the EMG2
 Works and Highway Works.
- 14.6.3. The potential effects on construction and maintenance workers during the construction phase of the **EMG2 Works** and **Highway Works** will be mitigated by appropriate protective site practices, such as dust suppression, safe storage of potential contamination, and the correct utilisation of appropriate PPE / RPE, which is deemed to be suitable. **Table 14.14** identifies the sensitivity of construction and maintenance workers as moderate. Assuming appropriate mitigation, the impact magnitude is Negligible (approximating to a 'no change' situation), with an associated Negligible significance of the effect.
- 14.6.4. Should unexpected contamination be encountered during the construction phase, the works in the area are expected to stop and the Local Authority and appointed geo-environmental consultant should be contacted, in accordance with draft DCO Requirement 22 (contamination risk). The contamination should be sampled, tested and risk assessed and, if required, a remediation strategy should be agreed, implemented and verified. This, therefore should mitigate the potential effects to future site commercial users, who are of low to moderate sensitivity, as well as the proposed hardstanding.
- 14.6.5. Soils that are to be potentially re-used on site are to be tested for geo-environmental and geotechnical suitability prior to re-use.
- 14.6.6. The Made Ground may be re-used as part of the earthworks, subject to appropriate sorting, segregation and classification testing and controlled placement in accordance with the earthworks specification, which should be prepared once design is finalised.
- 14.6.7. Any soils which are to be imported would also be required to have certification of their chemical concentrations to ensure that the imported soils are not introducing additional contaminants. This may be confirmed by soil chemical testing by the contractor and the associated earthworks to be controlled by engineering site specific specification.

- 14.6.8. Due to the shallow groundwater levels recorded during the groundwater monitoring rounds at the **EMG2 Works** and **Highway Works** (the latter presented within the Factual BWB PSSRs), appropriate dewatering measures should be considered throughout the construction phase. Dewatering measures should be put through the temporary drainage system as outlined within the CEMP.
- 14.6.9. The above mitigation measures will also mitigate the potential effects to off-site users (both residential and commercial), who may potentially be exposed to wind-blown dust during the construction phase. The effects on the high sensitivity off site residential users will be mitigated to negligible, provided the implementation of appropriate mitigation measures, such as dust suppression.

Construction Phase – MCO Application

- 14.6.10. The construction phase mitigation measures outlined above (Paragraphs 14.6.1 to 14.6.9) also apply to the MCO Application pertaining to the EMG1 Works. Albeit the additional mitigation measures for the EMG1 Works will arise from the CEMP for the development of Plot 16 to be approved pursuant to Regulation 11 of the with the EMG1 DCO and will accord with the construction management framework plan that has already been approved.
- 14.6.11. Dewatering measures should also be considered throughout the construction phase of the EMG1 Works, due to the shallow groundwater levels recorded within the ground investigation.

Operational Phase – DCO & MCO Application

- 14.6.12. Mitigation measures during the operational phase of both the DCO and MCO Application should focus on ongoing pollution prevention and site stability.
- 14.6.13. This is to include the following:
 - Good housekeeping practises ensuring all developments comprising the EMG2
 Project are kept clean and tidy and free of any debris;
 - Any fuels, lubricants, solvents, chemicals etc. should be stored in appropriately bunded areas / with drip trays beneath and appropriate pollution prevention measures should be put in place and adhered to, including on site spill kits.
 - Any hazardous materials which are to be stored across the EMG2 Project should be clearly labelled, segregated and stored in designated impermeable areas.
 - Where there is any evidence of damage / degradation to the hardstanding surfaces across the EMG2 Project, the damage should be repaired and reinstated promptly and as necessary.

14.7. Residual Effects

14.7.1. Residual effects are those that would remain after the implementation of the proposed mitigation measures. Each identified impact has been assessed within this Chapter including the associated mitigation and therefore, the residual effects are presented within Paragraphs

- 14.5.7 and 14.5.12 (construction and operational effects DCO Application) and Paragraphs 14.5.14 and 14.5.18 (construction and operational effects MCO Application). These effects are presented at the end of this Chapter within **Table 14.15**.
- 14.7.2. The effects of climate change on ground conditions should be considered, predominantly through alterations in rainfall patterns and an increase in temperature. These, in turn, are likely to result in a variety of effects to groundwater, including the shortening of the groundwater recharge season, increased groundwater flooding (in areas of adequate infiltration) and potential long term declines in groundwater storage. Chapter 19: Climate Change (Document DCO 6.19/MCO 6.19) includes a more detailed assessment of the impact of climate change on the EMG2 Project. Furthermore, the local groundwater bodies and the EMG2 Project's potential impact on their Water Framework Directive (WFD) status are discussed within Chapter 13: Flood Risk and Drainage (Document DCO 6.13/MCO 6.13).

14.8. Cumulative Effects

- 14.8.1. Inter-Project Effects are the interactions between all of the different developments (past and present) within the same area, which individually may not be significant, but when considered together could create a significant cumulative effect on a shared receptor.
- 14.8.2. Chapter 21: Cumulative Effects (Document DCO 6.21/MCO 6.21) sets out the methodology and scope of the cumulative assessment and outlines a Zone of Influence for each of the environmental aspects identified, considering the ground conditions across the EMG2 Project which have been identified in this Chapter.
- 14.8.3. The inter-project effects have been assessed based on methodology outlined in PINS Advice Note 17 in the aforementioned Chapter. Paragraph 21.4.3 of the Chapter considers a total of 12 sites in relation to inter-project effects (**Document DCO 21A/MCO 6.21A**).
- 14.8.4. It is assumed that similar mitigation measures will be incorporated and adhered to for these developments, in accordance to best practise and legislation. Therefore, the inter-project effects of such surrounding site developments are considered unlikely to effect the ground conditions across the **EMG2 Project**.

14.9. Summary of Effects and Conclusions

- 14.9.1. To summarise, the **EMG2 Project** is not anticipated to have significant adverse effects upon ground conditions provided there are appropriate mitigation measures in place.
- 14.9.2. The baseline conditions at the **EMG2 Works** and **Highways Works** (DCO Application) and **EMG1 Works** (MCO Application) have been informed through desk based and intrusive investigation findings, which in turn have informed the appropriate recommended mitigation measures throughout the construction and operational phases.
- 14.9.3. The mitigation measures to be completed during the construction phase of the DCO Application include:

- General construction phase mitigation, to mitigate the potential exposure to construction workers during the progression of the development, including the development of and adherence to a site health and safety plan, pre-approved RAMS, personal hygiene and welfare, correct PPE/RPE, decontamination measures if necessary, the safe and recorded storage of fuels/oils and any other potentially contaminative liquids, and regular cleaning of all site roads. These measures are detailed within the Construction Environmental Management Plan (CEMP) prepared for the EMG2 Works and Highway Works pertaining to the DCO Application (Document DCO 6.3A).
- Mitigation measures presented within the CEMP and submitted as part of the DCO Application, intend to limit the volume of potential silt laden run-off throughout the Earthworks. This includes the management of machinery and material movement (e.g. designated machine and dumper tracking routes), control of stockpiled materials (e.g. maximum height of 2.0 m, stockpiles must be sufficiently compacted and should be temporarily covered with the use of a seal), the use of temporary plot drainage (temporary settling basins with silt management deployment techniques) and the completion of monitoring procedures and records.
- Selection of appropriate materials for buried water supply pipes across the EMG2
 Works and Highway Works.
- Due to the shallow groundwater levels recorded during the groundwater monitoring rounds at the EMG2 Works and Highway Works (the latter presented within the Factual BWB PSSRs), appropriate dewatering measures should be considered throughout the construction phase. Dewatering measures should be put through the temporary drainage system as outlined within the CEMP.
- Soils that are to be potentially re-used on site are to be tested for geo-environmental
 and geotechnical suitability, comprising part of the site materials and waste
 management plan submitted as part of this application (subject to Chapter 18:
 Materials and Waste, Document DCO 6.18/MCO 6.18).
- The Made Ground may be re-used as part of the earthworks, subject to appropriate sorting, segregation and classification testing and controlled placement in accordance with the earthworks specification, which should be prepared once design is finalised.
- Any soils which are to be imported would also be required to have certification of their chemical concentrations to ensure that the imported soils are not introducing additional contaminants. This may be confirmed by soil chemical testing by the contractor and the associated earthworks to be controlled by engineering site specific specification.
- 14.9.4. The mitigation measures to be implemented during the construction phase of the MCO Application include:
 - The construction phase mitigation measures outlined above, with the additional mitigation measures for the EMG1 Works arising from the CEMP that was approved within the EMG1 DCO.

- 14.9.5. The mitigation measures to be implemented during the operational phase of both the DCO and MCO Application (**EMG2 Project**) include:
 - Good housekeeping ensuring all developments are kept clean and tidy and free of any debris (reducing the potential for leachate);
 - Any fuels, lubricants, solvents, chemicals etc. should be stored in appropriately bunded areas / with drip trays beneath and appropriate pollution prevention measures should be put in place and adhered to, including on site spill kits.
 - Any hazardous materials which are to be stored across the EMG2 Project should be clearly labelled, segregated and stored in designated impermeable areas.
 - Where there is any evidence of damage / degradation to the hardstanding surfaces across the EMG2 Project, the damage should be repaired and reinstated promptly and as necessary.
- 14.9.6. With reference to the sensitivity of identified receptors, magnitude of potential impacts and mitigation measures that may apply, the potential effects during the construction and operational phases are summarised within **Table 14.15** below. This table is separated into the DCO and MCO Applications. It is considered that there aren't any cumulative effects. Therefore, the intra-project cumulative effects presented within the Table have been combined.
- 14.9.7. Based on the implementation of the mitigation measures specified within this Chapter (included embedded mitigation measures), it is considered that there will not be significant effects of ground conditions on the identified receptors for the DCO Application, MCO Application, or the combined **EMG Project**.

Table 14.15: Summary of Potential Effects

Receptor	Sensitivity	Activity	Effect	Mitigation	Magnitude of Impact	Significance of effect	Additional mitigation	Significance of residual effect	
DCO Application	DCO Application – EMG2 Works and Highway Works								
Construction / maintenance workers	Moderate / low	Groundworks	Potential human health exposure to contaminated soils and groundwater	Adhere to good working practice and correct and appropriate use of PPE / RPE*	Negligible	Negligible	None	Negligible	
Surrounding off- site users (residential)	High		Exposure through indirect pathways, e.g. ingestion of air borne dust	Good site working practices, including dust management, for example through dampening with use of a fine spray*.	Negligible	Negligible	None	Negligible	
Surrounding off- site users (commercial)	Low								
Controlled surface waters: Diseworth Brook 320 m S and Long Whatton Brook, 500 m SE, on site drainage ditches	Moderate		Potential for contamination identified to adversely affect receptor	Where unexpected contamination is encountered, the works should cease and LA and geo-environmental consultant to be contacted, in accordance with requirement 22 (Land Contamination). The contamination to be sampled, tested and risk assessed and remedial strategy to be agreed, if required*. It is understood that piled foundations may be proposed within the Junction 24 improvements of the Highway Works. If the foundations are to be directly piled into the Principal Aquifer, a	Negligible	Negligible	None	Negligible	
Controlled Waters: Principal Aquifer	High				Negligible	Negligible	None.	Negligible	
Controlled Waters (non- potable aquifers): Secondary A Aquifer within Glaciofluvial Deposits and Secondary B Aquifer within the Gunthorpe	Moderate				Negligible	Negligible	None	Negligible	
Member)				Principal Aquifer, a Foundation Works Risk					

				Assessment may be required. The Silt Management Plan submitted as part of the CEMP, outlines mitigation measures to be implemented in the construction phase, for example the use of temporary drainage.				
Site maintenance workers	Moderate	Maintenance involving breaking ground / excavation	Exposure potential to residual contamination post construction	Much of the proposed development to be hard landscaping, use of correct PPE / RPE*	Negligible	Negligible	None	Negligible
Future commercial site users	Moderate	Presence on Site / Direct Contaminant Pathway	Introduction of new human health receptors on site (commercial workers)	The majority of the EMG2 Works and Highway Works development comprises impermeable hardstanding. No significant contamination was revealed during the site investigation.	Negligible	Negligible	None	Negligible
MCO Application	– EMG1 Wor	ks				•	1	
Construction / maintenance workers	Moderate / low	Groundworks	Potential human health exposure to contaminated soils and groundwater	Adhere to good working practice and correct and appropriate use of PPE / RPE.	Negligible	Negligible	None	Negligible
Surrounding off- site users (residential)	High		Exposure through indirect pathways, e.g. ingestion of air	Good site working practices, including dust management, for example	Negligible	Negligible	None	Negligible
Surrounding off- site users (commercial)	Low		borne dust	through dampening with use of a fine spray.				
Controlled Waters (non- potable aquifers):	Moderate		Exposure to soil contamination and potential	Where unexpected contamination is encountered, the works should cease and LA and	Negligible	Negligible	None	Negligible

Secondary A Aquifer within Eggington Common Sand and Gravel Member, Wanlip Member and Arden Sandstone Formation, Secondary B Aquifer within Tarpoley Siltstone and Edwalton Member, Secondary Undifferentiated Aquifer within Head Deposits.			contamination pathway	geo-environmental consultant to be contacted, in accordance with requirement 22 (Land Contamination). The contamination to be sampled, tested and risk assessed and remedial strategy to be agreed, if required.				
Site maintenance workers	Moderate	Maintenance involving breaking ground / excavation	Exposure potential to residual contamination post construction	Much of the proposed development to be hard landscaping, use of correct PPE / RPE.	Negligible	Negligible	None	Negligible
Future commercial site users	Moderate	Presence on Site / Direct Contaminant Pathway	Introduction of new human health receptors on site (commercial workers)	Ground gas protection measures to CS2 of BS8485 (EMG1 Works - Plot 16 warehouse), majority of proposed development comprises impermeable hardstanding and no significant contamination was revealed during the ground investigation.	Negligible	Negligible	None	Negligible

Notes: *Mitigation method refers to the best / safe practices and measures outlined within the CEMP for the **EMG2 Works** and **Highway Works** (**Document DCO 6.3A**) which includes the Outline Silt Management Plan. The additional mitigation measures regarding the MCO Application (**EMG1 Works**) have been approved with the EMG1 DCO.

